



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24110411/Uqh3m4
75 BRAS BASAH ROAD	Date:	10/12/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLB 7215Z	Veh. Inspected	SNM 6387K
Policy No.	-	Coverage	0
Claim No.	MT/1304464-002	Excess	\$0.00
Assign From	EILEEN LEE	Assign Date	19/11/2024

### 2. Vehicle Details

Make & Model	KIA NIRO SG2 HYBRID 1.6 SX (A)	C.C	1580
Engine No.	G4LLPS126906	Year of Reg.	09/10/2023
Chassis No.	KNACT81EVR5110251	Colour	GREY
Odometer	29553 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/60R16	NEXEN	7
L/H Front Tyre	205/60R16	NEXEN	7
R/H Rear Tyre	205/60R16	NEXEN	7
L/H Rear Tyre	205/60R16	NEXEN	7

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	15/11/2024	Inspection Date	29/11/2024 (12:21)
Survey held at	IMPERIUM AUTOMOTIVE 25 KAKI BUKIT ROAD 4 #01-49 SYNERGY @ KB SINGAPORE 417800		

5a. Remarks
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days