

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBC87K
Accident Date : 19-Nov-2024

Our Ref : 024227 (CHINA) / CHAN

SOH SWEE KIM
BLK 107 BUKIT BATOK WEST AVE 6
#06-102
Singapore 650107

Not Authorized
11 Sep 8 5400hr
Running After Repair
5 days

No. : 07210

Date : 20-Nov-2024

PAGE : 1

ESTIMATED COST OF REPAIR FOR HYUNDAI ELANTRA SDH5573R

1 pc Bonnet		<i>Bz</i> 1,125.00 ✓
1 pc Bonnet stand		<i>R</i> 32.00 X
1 pc Bonnet insulator		<i>Sn</i> 175.00 Z
1 pc Bonnet inner lock		<i>Ry</i> 105.00 Z
1 pc Bonnet front rubber		<i>Gr</i> 35.00 ✓
1 pc Front grille		<i>CM</i> 128.00 ✓
1 pc Front bumper fascia		<i>CM</i> 445.00 ✓
2 pcs Front bumper side top bracket @ S\$ 25.00		<i>Dr</i> 50.00 ✓
1 pc Front bumper sponge		<i>CM</i> 105.00 ✓
1 pc Front bumper reinforcement		<i>R</i> 516.00 Z
1 pc Front bumper lower beam		<i>R</i> 140.00 Z
1 pc Front bumper lower grille		<i>CM</i> 165.00 ✓
2 pcs Front bumper side retainer @ S\$ 20.00		<i>Sn</i> 40.00 X
2 pcs Headlamp - <i>CM</i> @ S\$880.00		<i>Bz</i> 1,760.00 Z
1 pc Front support panel		<i>Ry</i> 975.00 ✓
1 pc Air con condenser		<i>Ry</i> 895.00 ✓
2 pcs Air con condenser side guide @ S\$ 26.00		<i>Dr</i> 52.00 ✓
1 pc Radiator assy		<i>Hous Br</i> 520.00 Z
1 pc Radiator top hose		<i>Sn</i> 32.00 X
1 pc Radiator adaptor		<i>CM</i> 48.00 Z
1 pc Radiator adaptor hose		<i>Sn</i> 32.00 X
1 pc Radiator fan assy		<i>Sn</i> 568.00 X
		7,943.00
Less 20% :		1,588.60

1 pc Front no.plate with box

6,354.40
Ry 50.00 *sn*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBC87K

Page : 2

1 pc Radiator coolant	<i>Mr</i> 30.00 <i>sn</i> ✓
1 pc Front bumper clip (set)	<i>Mr</i> 30.00 <i>sn</i> ✓
To towing	60.00 ✓
To rewire damaged parts and refocus headlamp beam.	20.00 ✓
To remove air con condenser, pipes and drier, vacuum and to recharge gas	120.00 <i>100</i>
To putty and spray replaced parts	900.00 <i>750</i>
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts	1,000.00 <i>600</i>
Total :	S\$ 8,564.40

Singapore Dollars Eight Thousand Five Hundred and Sixty Four and Cents Forty Only