

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile MS LONPAC INSURANCE BHD Ref: CS3/LPC24110420/Rnh3e2 300 BEACH ROAD Date: 26/11/2024 #17-04/07 THE CONCOURSE SINGAPORE 199555 LPC2 Code: 1. **Policy Particulars :- PRE-REPAIR SURVEY** Insured Veh. YR 412D Veh. Inspected YP 371Z Z24VC05024558 Policy No. Coverage 0 Claim No. 24/24/VC05/030130 **Excess** \$0.00 **Assign From ERIC** Assign Date 20/11/2024 2. **Vehicle Details** C.C Make & Model ISUZU NMR85UH5A 2999 Engine No. 4JJ12D1186 Year of Reg. 01/12/2015 Chassis No. WHITE JAANMR85HF7103197 Colour Odometer 228546 KM IN ORDER Steering **Brakes** IN ORDER **FAIR** General Modification(s) RIMS: NIL **Conditions of Tyres** 3. Size Make Balance (mm) 7.00 R16 **PIRELLI** 7 **R/H Front Tyre** 7 L/H Front Tyre 7.00 R16 **PIRELLI** R/H Rear Tyre 7.00 R16 (D) **PIRELLI** 7/7 7/7 L/H Rear Tyre 7.00 R16 (D) **PIRELLI Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION 5. **General Information Accident Date** 29/10/2024 **Inspection Date** 21/11/2024 (10:07) Survey held at TMF AUTOMOTIVE PTE LTD - 231A PANDAN LOOP, SINGAPORE 128419 5a. Remarks A) MARKET VALUE: \$17,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$2,179.00=NETT VALUE: \$14,821.00 B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.

MRB

MOHAMMED RASUL BIN MOHD YUNUS

D) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.