

MCR MOTORS PTE.LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT

#01-53 SINGAPORE 415875

Vehicle number: SNU1009T

Make & Model: Honda Civic

Chassis number: MRHFC1660JT000162

No.	Description of spare parts	Qty	Amount S\$
1	Front bumper	1	\$ tn ✓ 617.20
2	Front bumper clips	1set	\$ re ✓ 70.00
3	Front bumper upper rubber seal	1	\$ x } x 27.60
4	Front bumper LH side retainer	1	\$ x } m 14.50
5	Front bumper RH side retainer	1	\$ x } 14.50
6	Front LH fender	1	\$ bt ✓ 450.00
7	Front LH fender signal lamp	1	\$ af ✓ 33.80
8	Front LH fender splash shield	1	\$ unf ✓ 33.90
9	Front LH fender splash shield clips	1set	\$ 2one ✓ 70.00
10	LH headlamp assy	1	\$ x } 1,428.90
11	LH headlamp garnish	1	\$ x } m 23.00
12	LH headlamp lower bracket	1	\$ x } x 25.90
13	Front LH sport rim (Original)	1	\$ ant ✓ 785.40
14	Front LH wheel bearing	1	\$ x } 83.40
15	Front LH shock absorber	1	\$ x } 289.60
16	Front LH lower arm	1	\$ x } 281.90
17	Front LH lower arm ball joint	1	\$ x } x 68.70
18	Front LH tie rod end	1	\$ x } m 89.30
19	Front LH knuckle arm	1	\$ x } 343.20
20	Front LH drive shaft	1	\$ x } 984.80
21	Sterering rack and pinion	1	\$ x } 1,321.10
			1184.90
			947.92

\$ 7,056.70
 Parts less 20% \$ 1,411.34
 Total: \$ 5,645.36

No.	Special Nett Items	Qty	Amount S\$
1	Front LH tyre	1	\$ x m 500.00
2	Brake fluid	1	\$ x m 80.00

		Total:	\$ 580.00

No.	Labour and painting	Amount S\$
1	Labour charges to the affected and consistent areas	\$ 300 1,200.00
2	Spray painting on affected and consistent areas and panels	\$ 400 1,000.00
3	Check wiring and lighting system on affected areas	\$ 30 70.00
4	Apply rust coating chemical on affected areas and panels	\$ 30 60.00
5	Test drive and adjust wheel alignment system	\$ 80 120.00
6	Remove and replace front undercarriage parts to assist repair	\$ X ⁿⁿ 450.00
7	Refocus and adjust headlamps assy	\$ X ⁿⁿ 60.00
		840
Total labour		\$ 2,960.00

Tanjong 97495749 / 62563561

WP 20/11/24 24pm

3 days

4/5 Resurvey after repair

Tanjong @ Tuhando.com

- To check consistency of accident
- To check part prices.

Total: \$ 9,185.36

147.92

840

1787.92

4/5 \$1400

3 days

X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: