



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909 ATTN: IRENE TAY			Ref: CS/CTI24110426/Kqh3m4(N) Date: 27/11/2025 Code: CTI	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SLU 9006Y
	Policy No.	DMPCSNW00135382300	Coverage (\$)	0.00
	Claim No.	SNM24D206258	Excess (\$)	500.00
	Assign From	IRENE TAY	Assign Date	20/11/2024
2. Vehicle Particulars & Condition				
	Make & Model	KIA SORENTO 2.2(8AT) CRDI 2WD S/R	c.c	2199
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	KNAPH81BMJ5411495	Colour	METALLIC RED
	Odometer	194741 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/60R18	CONTINENTAL	7 mm
	L/H Front Tyre	235/60R18	CONTINENTAL	7 mm
	R/H Rear Tyre	235/60R18	CONTINENTAL	6 mm
	L/H Rear Tyre	235/60R18	CONTINENTAL	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	06/11/2024	Inspection Date	20/11/2024
	Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks				
	A)THE MARKET VALUE IS S\$68,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	