

Auburn Auto Pte Ltd

176 Sin Ming Drive
#04-18 Sin Ming AutoCare
Singapore 575721
UEN:200805305G
Email: AuburnAuto.Insurance@gmail.com

Not Withheld
L1 Rep & 2350h
Resing After Pain
4 days

TO: ECICS LIMITED
ATTN.: MOTOR CLAIMS DEPARTMENT
OUR REF.: SKW4268S
YOUR REF.: SNF7845K

DATE: 26/11/2024
VEHICLE NO.: SKW4268S
MAKE & MODEL: NISSAN SYLPHY
DATE OF ACC.: 17/11/2024
CLAIM TYPE: TP

ESTIMATE FOR VEHICLE NO.: SKW4268S

NO.	DESCRIPTION	QTY.	LIST PRICE	TOTAL PRICE
<u>PARTS</u>				
1	FRONT BUMPER 739	1	\$ 1,447.00	\$ CM 1,447.00 ✓
2	FRONT BUMPER GRILLE LEFT	1	\$ 302.00	\$ in 302.00 X
3	FRONT BUMPER REINFORCEMENT BRACKET LEFT	1	\$ 174.00	\$ n 174.00 X
4	FRONT SUPPORT PANEL	1	\$ 991.40	\$ n 991.40 X
5	FRONT SUPPORT PANEL TOP GARNISH	1	\$ 375.00	\$ in 375.00 X
6	HEADLAMP	1	\$ 120.00	\$ in 120.00 ✓ 1180.00
7	HEADLAMP LOWER BRACKET	2	\$ 65.00	\$ in 130.00 X
SUBTOTAL:				\$ 3,539.40
LESS 10%:				\$ 707.88
PARTS TOTAL:				\$ 2,831.52

<u>SPECIAL NETT</u>				
1	FRONT BUMPER CLIPS	1 SET	\$ 50.00	\$ n 50.00 ✓
2	FRONT SUPPORT PANEL TOP GARNISH CLIPS	1 SET	\$ 50.00	\$ n 50.00 X
3	FRONT NUMBER PLATE SET	1 SET	\$ 50.00	\$ ncl 50.00 451n
SPECIAL NETT TOTAL:				\$ 150.00

LABOUR

TO REMOVE, REFIT & INSTALL ALL ACCIDENT AFF. PORTIONS	\$	n 120.00 X
TO REMOVE & REFIT AIRCON ASSY, VACUUM AND TOP UP GAS	\$	n 120.00 X
TO CHECK ALL NECESSARY WIRING	\$	100.00 201
TO REMOVE & REFIT HEADLIGHT ASSY	\$	120.00
TO PANEL BEAT ON AFF. PORTIONS	\$	1,000.00 500
TO PUTTY & RESPRAY ALL ACCIDENT AFF. PORTIONS	\$	1,200.00 600
TO APPLY COATING ON ALL ACCIDENT AFF. PORTIONS	\$	n 150.00 X
LABOUR TOTAL:		\$ 2,810.00
GRAND TOTAL:		\$ 5,791.52

BEFORE 9% GST

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: