

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

RM 500

Name : **Kuhan A/L Tavamasan**
(971543310)

Accident Date : **12-Nov-24**

Vehicle No : **jvr5780 (dor: 17102022)**

Vehicle Model : **Yamaha Y15ZR**

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
2	Front fork tube assy	520 \$ Buffer 640.00 ✓
1	Fork under bracket	100 \$ Buf 185.00 ✓
1	Front fender	80 \$ Cu 125.00 ✓
1	Front wheel rim	\$ R 380.00 X
1	Front rim shaft	\$ Su 65.00 X
1	Front rim bearing	\$ 1 90.00 X
1	Front brake disc	\$ 1 185.00 X
1	Handle bar	\$ Buf 165.00 ✓
1	Handle-bar end (1 set)	40 \$ Cu 105.00 ✓
1	Hand grip (1 set)	100 \$ MS 85.00 X
1	Headlamp assy	\$ 1 580.00 X
1	Mirror	80 \$ Buf 150.00 ✓
1	Brake lever	\$ Cu 85.00 ✓
1	Front signal (1 set)	100 \$ Cu 140.00 ✓
1	Pilot lights	\$ Cu 228.00 ✓
1	Basket	60 \$ Buf 125.00 ✓
1	Front horn inner cover centre matt black	\$ 1 85.00 X
1	Front horn inner cover	\$ 1 135.00 X
1	Pillions footrest bracket	\$ Su 180.00 X
1	Pillion footrest (1 set)	\$ Cu 98.00 ✓
1	Engine cover	550 \$ Cu 685.00 ✓
1	Exhaust cover	\$ Cu 115.00 ✓
1	Exhaust end cap	\$ Cu 75.00 ✓
1	Rider footrest(1 set)	\$ Su 88.00 X
1	Rider footrest bracket (1 set)	\$ 1 170.00 X
1	Brake pedal	\$ Cu 125.00 ✓
1	Fairing assy (1 set)	520 \$ Cu 580.00 ✓
		\$ 5,669.00
	Less 10%	\$ 566.90
		\$ 5,102.10

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : **Kuhan A/L Tavamasan**
(971543310)

Accident Date : **12-Nov-24**

Vehicle No : **jvr5780 (dor: 17102022)**

Vehicle Model : **Yamaha Y15ZR**

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	\$ 11	38.00X
2	Fork oils	\$ 11	30.00X
2	Fork oil seals	\$ 11	56.00X
1	Steering cone (1 set)	\$ 22	95.00 60
1	Sticker set	\$ 22	120.00 60
		\$	339.00

S/No. Labour

1	To provide towing service (LOD) \$40.00	refer to LOD	\$	-	X
2	To check wiring and reset headlamp focusing		\$	11	80.00 X
3	To repair body frame		\$	11	480.00 X
4	To provide labour		\$	480.00	300
			\$	1,040.00	

Grand Total

\$ 6,481.10

Singapore Dollars: Six Thousand Four Hundred Eighty-One and Cents: Ten only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7-3019
1076
2717.10
120
300
3137.1
212
2509