

LHK

not Anthony

in
mea's

21/11/24

4/s 35w
4 days.

The photo. Attached.

Accident Date : 17-Nov-24

Triumph Street

Vehicle Model : **Tripler R675**
Manual

Estimated Repair Costs

Qty	Description	Amount S(\$)
1	Windshield	\$ 500 485.00
1	Clutch lever	200 \$ 450.00
1	Side mirror	180 \$ 280.00
1	Handle bar	420 \$ 680.00
1	Handle bar end	60 \$ 280.00
1	Hand grip (1 set)	\$ 155.00
1	Front footrest - L/H	\$ 320.00
1	Front footrest bracket	\$ 755.00
2	Rear footrest	\$ 280.00
1	Rear footrest bracket	280 \$ 680.00
1	Exhaust assy	1800 200 \$ 2,800.00
1	Rear signals (1 set)	120 \$ 420.00
1	Engine cover	900 \$ 1,280.00
		\$ 9,105.00
	Less 10%	\$ 910.50
		\$ 8,194.50

Special Nett Items

1 *Rev* Number Plate (1 set)

benf \$ 38.00 20 s/n
\$ 38.00

S/No.	Labour	
1	To provide towing (LOD) S\$70.00	\$ -
2	To check wiring and reset headlamp focusing	\$ 17 80.00 X
3	To repair body frame	\$ 17 580.00 X
4	To provide labour and repair front fork	\$ 680.00 } 80
		\$ 1,340.00
		\$ 9,572.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey

Grand Total

Singapore Dollars: Nine Thousand Five Hundred Seventy-Two and Cents: Fifty only

$$\begin{array}{r} 1-4455 \\ \underline{107} \\ 4009.50 \\ 20 \\ \underline{380} \\ 4409.5 \\ 3127 \end{array}$$

EROFIA MOTOR TRADING PTE LTD

Acknowledged by Repairer

Signature: _____ Page 1 of 1

Page 1 of 1