

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile MS INCOME INSURANCE LTD Ref: CS/INC24110447/Uvh3m4 75 BRAS BASAH ROAD Date: 12/12/2024 INCOME CENTRE SINGAPORE 189557 Code: INC 1. Policy Particulars:- THIRD PARTY CLAIM Insured Veh. FBP 2344L Veh. Inspected FBV 2699G Policy No Coverage 0 Claim No. MT/1304665-002 Excess \$0.00	
75 BRAS BASAH ROAD INCOME CENTRE SINGAPORE 189557 Date: 12/12/2024 Code: INC 1. Policy Particulars :- THIRD PARTY CLAIM Insured Veh. FBP 2344L Veh. Inspected FBV 2699G Policy No. - Coverage 0	
INCOME CENTRE SINGAPORE 189557 Code: INC 1. Policy Particulars :- THIRD PARTY CLAIM Insured Veh. FBP 2344L Policy No Coverage 0	
Code: INC	
Insured Veh. FBP 2344L Veh. Inspected FBV 2699G Policy No Coverage 0	
Insured Veh. FBP 2344L Veh. Inspected FBV 2699G Policy No Coverage 0	
Policy No Coverage 0	
Assign From MARCUS Assign Date 20/11/2024	
2. Vehicle Details	
Make & Model TRIUMPH STREET TRIPLE R 675 MANUAL C.C 675	
Engine No. VEDA02316 Year of Reg. 19/03/2009	
Chassis No. SMTTMD41669398587 Colour ORANGE	
Odometer 50048 KM Steering IN ORDER	
Brakes IN ORDER General GOOD	
Modification(s) RIMS: SPORTS RIM	
3. Conditions of Tyres	
Size Make Balance (mm)	
R/H Front Tyre 120/70ZR17 BRIDGESTONE 6	_
L/H Front Tyre	
R/H Rear Tyre 190/55ZR17 BRIDGESTONE 6	
L/H Rear Tyre	
L/H Rear Tyre 4. Description of Damages	
L/H Rear Tyre	
L/H Rear Tyre 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY.	
L/H Rear Tyre 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY. DAMAGES SEE DETAILS.	
L/H Rear Tyre 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY. DAMAGES SEE DETAILS. 5. General Information	
L/H Rear Tyre 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY. DAMAGES SEE DETAILS. 5. General Information Accident Date 17/11/2024 Inspection Date 21/11/2024 (10:42) Survey held at EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62	
L/H Rear Tyre 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY. DAMAGES SEE DETAILS. 5. General Information Accident Date 17/11/2024 Inspection Date 21/11/2024 (10:42) Survey held at EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.	
L/H Rear Tyre 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY. DAMAGES SEE DETAILS. 5. General Information Accident Date 17/11/2024 Inspection Date 21/11/2024 (10:42) Survey held at EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.	
L/H Rear Tyre 4. Description of Damages THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION AND N/S BODY. DAMAGES SEE DETAILS. 5. General Information Accident Date 17/11/2024 Inspection Date 21/11/2024 (10:42) Survey held at EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.	