

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/11124/10453/UV23

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

G3F680G

at Workshop m/s

Ling Lion Huat

of

Insured:

G3D807U

Policy No.

D24MFL0003653

Claims No.

MFL2024D0013897


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

8224.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.:

Yes or No

Lum Sum:

1.3.1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

158d

Vehicle: IN / OUT

Date:

Person Contacted:

L1086637

Veh No:

G3F680G

Yr Regn:

08/06/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Cm /

Make:

Toyota Dyna

c.c

2982

Colour:

Green / white

Insured / Std / NI / NA

Sp. Reading

282818

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KDY/23180*23932

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195-215

R:

165-213

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

hankook

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

8/11/24

D.O.I.

22/11/24

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/14.

5/12/24 P/P 8/085 inform shui (red 7400, 87%)
 NO 2nd hand parts only 2 items

Note:

No 2nd hand parts available

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip:

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	158D
Vehicle Details	
Vehicle No.:	GBF680G
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Nov 2024
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0 MANUAL
Primary Colour:	White
Manufacturing Year:	2016
Engine No.:	1KD2598476
Chassis No.:	KDY2318023932
Maximum Power Output:	-
Open Market Value:	\$32,638.00
Original Registration Date:	08 Jun 2016
First Registration Date:	08 Jun 2016
Transfer Count:	2
Actual ARF Paid:	\$1,632.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	07 Jun 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$43,002.00
COE Rebate Amount:	\$6,637.00
Total Rebate Amount:	\$6,637.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 22 Nov 2024

OK

Home/Used Cars/Listing

All Category

Filter

2

Search

Save Search

Any status X2016 X

Sort by Any Status, Date Posted (Newest)

15 Vehicles

Car Make

Car Model

Price Range

Depreciation

2016

Mileage

- 

Toyota Dyna 150 3.0M

\$30,800

Instl. \$1,616 /mth

\$18,890 /yr

11-Jul-2016 (1yr 7mths COE left)


N.Air

2,982 cc

4 Owners

Reliable Toyota manufacturer with no headache in maintenance! Guaranteed good resale value at end of COE! Class 3 license can drive with immaculate condition! Premium servicing/warranty with further lucrative provided! High loan 100% available or full cash welcome! Speedy loan approvals with immediate handover! Attractive trade in welcome. WhatsApp/call our sales consultant to view this beauty!

Car (S) Pte Ltd|Posted 20-Nov-2024

Compare
- 

Toyota Dyna 150 3.0M

\$29,800

Instl. \$1,292 /mth

\$15,190 /yr

09-Nov-2016 (1yr 11mths COE left)

N.Air

2,982 cc

2 Owners

ABWIN (1994) Pte Ltd|Posted 18-Nov-2024

Compare
- 

Toyota Dyna 150 3.0M

\$35,800

Instl. \$1,489 /mth

\$17,710 /yr

01-Dec-2016 (2yrs COE left)

N.Air

2,982 cc

1 Owner

G plate Toyota Dyna 3.0 manual in town. Excellent condition, install canopy available, low mileage done, 6 months warranty and servicing free, call now! Best solution for your commercial vehicle needs.

1F Motoring Pte Ltd|Posted 18-Nov-2024

Compare
- 

Toyota Dyna 150 3.0M

\$24,800

Instl. \$1,456 /mth

\$17,410 /yr

27-Apr-2016 (1yr 5mths COE left)

160,238 km

2,982 cc

1 Owner

Best for short-term usage! Most steady lorry in the market! All wear & tear replaced! Brand new paint work! Pristine condition to renew another 10years! Fast handover! Best offer for your vehicle! Flexible loan package! One stop solution for all your commercial vehicle needs! Contact our resourceful salesperson for any enquiries and we will make sure all your questions are answered!

Lek Auto Pte Ltd|Posted 18-Nov-2024

Compare

HUP LIAN HUAT ENGINEERING WORKS

No.38 Defu Lane 9, Singapore 539278
TEL: 6282 3336 (3 Lines) FAX: 6289 3336 Email: mahlian@singnet.com.sg
GST:52832105J RCB NO:201327339E

Not Authorized
22/11/24
P/P \$ 1085
2 days.

M/S : India International Insurance Pte Ltd

64 Cecil Street

#04/ #05/ #06-02

IOB Building Singapore 049711

TEL: 6347 6100

FAX: 6224 4174 / 6225

ATTN: Motor Claim Department

Estimate No: ES1602322

Date: 08 Nov 2024

Policy No: 2024-v5022802-vcv

Veh Reg No: GBF680G

Make/Model: TOYOTA DYNA 3.0
MANUAL

Chassis No: KDY2318023932

Engine No: 1KD2598476

Reg. Date: 08/06/2016

Your Ref No: WEE GUAN ENG PL

Claim Type: Third Party

Accident Date: 08/11/2024

TP Veh Reg No: GBD807U

Estimate Repair Cost to Vehicle No :GBF680G

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
Net Price				
1 Rear Tipper Door Tailgate	2,100.00	1 PC	2,100.00 X	
2 Rear Tipper Rubber Stopper -LH	100.00	1 PC	100.00 ✓	60 S/N
3 Rear Tipper Rubber Stopper Bracket -LH	1,800.00	1 PC	1,800.00 X	
4 Rear Tipper Lock	180.00	1 PC	180.00 X	
5 Rear Tipper Hinge	230.00	1 PC	230.00 X	
6 Rear Tipper Side Frame	950.00	1 SET	950.00 X	
7 Tail Lamp Assy -LH	190.00	1 PC	190.00 ✓	S/N
8 Tail Lamp Bracket -LH	250.00	1 PC	250.00 X	
9 Sticker " 70 km/h "	40.00	1 PC	40.00 10 S/N	
10 Sticker " Tailgate "	95.00	1 PC	95.00 ✓	S/N
11 Sticker " 8 Pax "	40.00	1 PC	40.00 10 S/N	
			5,975.00	5,975.00
Labour				
12 Labour to renew & refit all above parts .	1,000.00	1 -	1,000.00 300	
13 Labour to check & connect & rewire & renew tail lamp .	180.00	1 -	180.00 20	
14 To rust proofing at accident affected area .	380.00	1 -	380.00 X	
15 To spray & painting at accident affected area .	950.00	1 -	950.00 400	
			2,510.00	2,510.00
			Total	S\$ 8,485.00
			Add GST @ 9%	763.65
			Total Amount Payable	S\$ 9,248.65

TOTAL: SINGAPORE DOLLAR NINE THOUSAND TWO HUNDRED FORTY EIGHT AND CENTS SIXTY FIVE ONLY

the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For HUP LIAN HUAT ENGINEERING
WORKS

AUTHORISED SIGNATURE

S.N - 365
L - 720
1085