

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

email: erofia@singnet.com.sg

LKK

not Authorized
des
mercy
22/11/24

Name : Lim Yse Aik (83021095)

Accident Date : 18-Nov-24

Vehicle No : JPX377 (DOR: 16022014)

Vehicle Model : Kawasaki
ER250C

limited 1/2 @ 2200
4 days

Estimated Repair Costs

Qty	Description List Items		Amount S(\$)
1	Front fender	160 320	\$ 425.00 ✓
2	Fork tubes assy	1300 320	\$ 3,600.00 ✓
1	Fork under bracket	280 320	\$ 1,285.00 ✓
1	Front rim shaft	50	\$ 125.00 X
1	Fron rim bearing	11	\$ 95.00 X
1	Front brake disc	50	\$ 850.00 X
1	fuel tank	1480 320	\$ 2,050.00 ✓
1	Top cowling	305 320	\$ 945.00 ✓
1	Windscreen	180 320	\$ 360.00 ✓
1	Lamp stay	160 320	\$ 730.00 ✓
1	Headlamp - LED	1050 320	\$ 1,850.00 ✓
1	Meter assy	11	\$ 1,850.00 X
2	Side mirror (1 set)	11	\$ 530.00 X
2	Handle-bar (1 set)	80	\$ 710.00 X
2	Handle-bar end (1 set)	11	\$ 170.00 X
1	Hand grip (1 set)	11	\$ 75.00 X
1	Clutch lever	90 320	\$ 185.00 ✓
1	Front signals (1 set)	60x2x120 320	\$ 400.00 ✓
1	Side fairing (1 set)	820 320	\$ 1,610.00 ✓
1	Side fairing inner panel - L/H	60 320	\$ 180.00 ✓
1	Side fairing lower cover	11	\$ 480.00 X
1	Side fairing centre cover	11	\$ 185.00 X
1	Radiator	800 320	\$ 1,848.00 ✓
2	Front footrests	11	\$ 190.00 X
2	Front footrests brackets	11	\$ 290.00 X
1	Gear pedal	105 320	\$ 225.00 ✓
2	Rear footrest (1 set)	11	\$ 310.00 X
2	Rear footrest bracket (1 set)	11	\$ 640.00 X
			\$ 22,193.00
		Less 10%	\$ 2,219.30
			\$ 19,973.70

2- 6910

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

email: erofia@singnet.com.sg

Name : Lim Yse Aik (83021095)

Accident Date : 18-Nov-24

Vehicle No : JPX377 (DOR: 16022014)

Vehicle Model : Kawasaki
ER250C

Estimated Repair Costs

Special Net Items

1	Number plate (1 set) <i>for m/s</i>	\$	38.00	<i>10</i>
2	Fork oils <i>1 1</i>	\$	40.00	<i>X</i>
2	Fork oil seals <i>1 1</i>	\$	76.00	<i>X</i>
1	Steering cone (1 set) <i>new</i>	\$	120.00	<i>60</i>
1	Gasket <i>1 1</i>	\$	150.00	<i>X</i>
3	Engine oil <i>1 1</i>	\$	84.00	<i>X</i>
1	Front reflector <i>1 1</i>	\$	80.00	<i>X</i>
		\$	588.00	

S/No. Labour

1	To provide towing service (LOD) S\$50.00 <i>refer to road</i>	\$	-	
2	To check wiring and reset headlamp focusing	\$	<i>1 1</i> 80.00	<i>X</i>
3	To repair body frame	\$	<i>1 1</i> 420.00	<i>X</i>
4	To provide labour	\$	480.00	<i>300</i>
		\$	980.00	

Grand Total

\$ 21,541.70

Singapore Dollars: Twenty-One Thousand Five Hundred Forty-One and Cents: Seventy only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: