

EURO SUCCESS SERV PTE. LTD
Blk 1 Kaki Bukit 6, #02-03 Singapore 417883

TEL: 67426231 FAX: 67411019 H/P: 98289277 (AH HUAT)

Vehicle No: SMY3094Z

Model: BMW X1

Not Authorized
merans

22/11/24

3 days 4/5 & 4200
whelpke-Attorneys

QTY	List Items		Price \$
1	FRONT DOOR L/H	20/200	1385.00 ✓
1	FRONT DOOR LOCK ASSY L/H	11	420.00 X
1	FRONT DOOR WEATHERSTRIP L/H	11	186.30 X
1	FRONT DOOR INNER BOARD L/H	11	485.30 X
1	FRONT DOOR INNER BOARD CLIP (SET)	11	50.00 X
1	FRONT DOOR LOWER RUBBER L/H	11	86.40 X
1	FRONT DOOR GLASS L/H	750.00 CUT	990.00 ✓
1	SIDE MIRROR L/H	2542.77 CR	2750.80 ✓

TOTAL \$6,353.80
LESS 5% \$317.69
TOTAL \$6,036.11

LABOUR CHARGES

PANEL BEATING 1000.00 300
SPRAY PAINTING CHARGES 800.00 450
TO CHECK WIRING FOR PROPER FUNCTION 150.00 20
TO TRANSFER DOOR FITTING 200.00 60

TOTAL \$2,150.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL

\$8,186.11

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P. 4677.77

52

4443.89

830

5273.89

202

4119.