



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24110468/Kvh3e2
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	19/12/2024
SINGAPORE 048583	Code:	LIP

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 123Z	Veh. Inspected	YM 9738G
Policy No.	-	Coverage	0
Claim No.	IVS24/2183	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	21/11/2024

### 2. Vehicle Details

Make & Model	MITSUBISHI FE84 (M)	C.C	2977
Engine No.	4M42A64137	Year of Reg.	15/12/2008
Chassis No.	FE84BEA10280	Colour	WHITE
Odometer	509593 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	700 R16	OPARTNER	8
L/H Front Tyre	700 R16	OPARTNER	8
R/H Rear Tyre	700 R16 (D)	ARISUN	5/5
L/H Rear Tyre	700 R16 (D)	ARISUN	5/5

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	18/11/2024	Inspection Date	22/11/2024
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

### 5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days