

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

VEHICLE NUMBER: SKP2995B

MAKE & MODEL: VOLKSWAGEN GOLF

FRONT FENDER RH	R		\$769.10	X
FRONT RIM RH	17		\$1,846.00	X
FRONT LOWER ARM RH	17		\$678.10	X
FRONT KNUCKLE ARM RH	17		\$973.25	X
FRONT KNUCKLE BEARING RH	17		\$851.30	X
FRONT SHOCK ABSORBER RH	17		\$478.50	X
FRONT DOOR RH	Body 20	1615	\$2,224.60	X
FRONT DOOR WEATHERSTRIP RH	17		\$166.20	X
FRONT DOOR OUTER GLASS MOULDING RH	17		\$134.80	X
FRONT DOOR INNER GLASS SEAL RH	17		\$87.90	X
FRONT DOOR OUTER HANDLE RH	Body	280	\$756.19	X
FRONT DOOR LOCK CYLINDER WITH HOUSING	Body	305	\$419.95	X
FRONT DOOR OUTER HANDLE CAP RH	Body		\$56.40	X
FRONT DOOR INNER LOCK RH	17		\$343.64	X
FRONT DOOR SIDE MIRROR RH	Body		\$889.69	X
FRONT DOOR SIDE MIRROR COVER RH	17		\$257.40	X
REAR DOOR RH	Body 1911	1605	\$2,431.20	X
REAR DOOR WEATHERSTRIP RH	17		\$166.20	X
REAR DOOR OUTER GLASS MOULDING RH	17		\$134.80	X
REAR DOOR INNER GLASS SEAL RH	17		\$87.90	X
REAR DOOR OUTER HANDLE RH	R		\$234.20	X
			\$13,987.32	
			Less 10%	\$1,398.73
				\$12,588.59

FRONT FENDER INNER SPLASH SHIELD RH CLIPS	17	\$70.00	X
FRONT TYRE RH	17	\$350.00	X
FRONT DOOR TRIMBOARD RH CLIPS	17	\$80.00	X
REAR DOOR TRIMBOARD RH CLIPS	17	\$80.00	X
		\$580.00	

TO PROVIDE LABOUR, WORKMANSHIP	\$1,400.00	280
TO SPRAY PAINT ON AFFECTED PANELS	\$1,000.00	600
RUST PROOFING	\$80.00	50
TO REMOVE, REFIT & TRANSFER FRONT & REAR RIGHT DOORS TO	\$160.00	100
TO REMOVE, REPLACE FRONT RH SIDE MIRROR	17 \$80.00	X
TO CONDUCT COMPUTERISE DIAGNOSTIC, RESET AND	17 \$360.00	X
TO CONDUCT WHEEL ALIGNMENT	17 \$120.00	X
TO REMOVE & REPLACE FRONT RIGHT TYRE AND BALANCING	17 \$80.00	X
TO REMOVE AND REPLACE FRONT RIGHT UNDERCARRIAGE	17 \$280.00	X
	\$3,560.00	
	\$16,728.59	

Total

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorised
me
22/11/24
d/s @ 4200
Alphie Akhup
3 days

P-4751.09
102
4275.99
1030
5325.99
4244