



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: EILEEN

Ref: CS/INC24110475/Avh3e2(N)

Date: 21/04/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBA 7636R	Veh. Inspected	SU 5520L
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1305310-001	Excess (\$)	0.00
Assign From	EILEEN	Assign Date	22/11/2024

2. Vehicle Particulars & Condition

Make & Model	HONDA RS-X	c.c	149
Engine No.	HIDDEN	Year of Reg.	2024
Chassis No.	PMKKC43E0PB120454	Colour	BLUE
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	90/80 R17	CS	6 mm
L/H Front Tyre			mm
R/H Rear Tyre	120/70 R17	CS	6 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/11/2024	Inspect Date / Time	22/11/2024 (12:53 PM)
Survey held at	JEC AUTO SERVICE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-11 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days