

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	LIBERTY INSURANCE PTE LTD		Ref:	CS/LIP24110477/Tqp3e2	
	ONE RAFFLES QUAY #25-01 NORTH TOWER		Date:	23/12/2024	
	SINGAPORE 048583		Code:	LIP	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SLA 4191H	Veh. Inspected	FBM 9967J	
	Policy No.	-	Coverage	0	
	Claim No.	AVS24/2046	Excess	\$0.00	
	Assign From	ANDY SEAH	Assign Date	04/07/2024	
2.	2. Vehicle Details				
	Make & Model	YAMAHA GDR155A	C.C	155	
	Engine No.	G3J8E0050144	Year of Reg.	07/06/2018	
	Chassis No.	MH3SG4640JJ042449	Colour	BLUE	
	Odometer	- KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: NIL			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	120/60 R14	MAXXIS	4	
	L/H Front Tyre				
	R/H Rear Tyre	140/70 R14	MAXXIS	4	
	L/H Rear Tyre				
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	22/06/2024	Inspection Date	04/07/2024	
	Survey held at	ME NUT MOTOR - 5 SOON LEE STR	EET #02-04 PIONE	ER POINT SINGAPORE 627607	
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
Du. Latiniate Daya Of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days