

ASS. REC. BY:

REF: CS/ICS24110479/Rup3

6481

ASSIGNMENT

From:

Date:

Estimated Cost:

OB / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKF 69984

at Workshop m/s SKH M PCK

of PIONEER RD NORTH

Insured:

ICS

Policy No.

Claims No.

Sum Insured:

Excess:


750

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

165K

IDAC Accident Report:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

REPAIR LIMIT - 81K

Veh No:

SKF 69984

Yr Regn:

2019 ID6C

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MERCEDES BENZ E300 AV4 c.c. 1991

Colour:

WHITE

A/C: Insured / Std / NI / NA

Sp. Reading:

142934

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WDD2130832A728568

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

245/45R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

19/11/24

D.O.I.

26/11/24

Survey held at

PIONEER RD NTH

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Order/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

Order/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐
☐
☐
☐

: Site Insp (\$

: Interview (\$

: Tech. Invs (\$

: Weekend (\$

) S + RS \$

) Photos

) Other

Report Format:

Lump Sum / L.B.I. (\$

TOTAL

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No:200810440N)

Blk 3 Pioneer Road North, #01-18
Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email:

sngahtee@singnet.com.sg;darren@sngahtee.com;admin@sngahtee.com;admin2@sngahtee.com

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC23A00375400	Date of Loss:	19/11/2024
Vehicle Reg. No.:	SKF6998U	Driveable?	
Driver Age/Info:	48 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ZHOU HAILONG	Contact No:	+6590064528
Driver:	ZHOU HAILONG		

Make/Model:	MERCEDES-BENZ E300, 2.0 (A)	Vehicle Reg. Date:	17/12/2019
Vehicle Colour:	WHITE		
Engine No:	26492080016553	Chassis No:	WDD2130832A728568
Odometer:	142235 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	8

Description of Accident/Loss	ON 19/11/2024 @
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)

COST OF CLAIMS	Amount
Parts	12,031.60
Miscellaneous Items	0.00
Labour	1,530.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	13,561.60
+ GST 9.00% (S\$)	1,220.54
Nett Amount (S\$)	14,782.14

This claim is handled by: JOYCE TAN LAI CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Nov 2024)

Parts: M1-COUPE MERCEDES-BENZ E300 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/SKF6998U/21/11/2024 14:11

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT NUMBER PLATE <i>de</i>	0	0.00	*35.00 FS
2	1		*FRT NUMBER PLATE HOLDER <i>de</i>	0.00	0.00	*105.00 F
3	1		*FRT BUMPER <i>de</i>	0.00	0.00	*1,175.00 F
4	2		*FRT BUMPER RETAINER LH/RH ?	0.00	0.00	*20.00 F
5	1		*FRT BUMPER LOWER CENTER CARRIAGE ?	0.00	0.00	*118.00 F
6	1		*FRT BUMPER LWR CENTER TRIM <i>de</i>	0.00	0.00	*95.00 F
7	1		*FRT BUMPER SPONGE ?	0.00	0.00	*150.00 F
8	1		*FRT GRILLE ASSY <i>cm</i>	0.00	0.00	*165.00 F
9	1		*FRT GRILLE OUTER CENTER MOULDING <i>cm</i>	0.00	0.00	*225.00 F
10	4		*FRT GRILLE OUTER CENTER TRIM <i>cm</i>	0.00	0.00	*260.00 F
11	1		*FRT GRILLE OUTER TRIM <i>cm</i>	0.00	0.00	*210.00 F
12	1		*FRT GRILLE EMBLEM <i>cm</i>	0.00	0.00	*105.00 F
13	1		*FRT GRILLE EMBLEM BASE ?	0.00	0.00	*78.00 F
14	1		*FRT CAMERA ?	0.00	0.00	*1,150.00 F
15	1		*FRT CAMERA CAP ?	0.00	0.00	*10.00 F
16	2		*FRT PARKING AID SENSOR CENTER LH/RH ?	0.00	0.00	*270.00 F
17	1		*FRT BONNET <i>st</i>	0.00	0.00	*1,645.00 F
18	1		*FRT BONNET EMBLEM <i>cm</i>	0.00	0.00	*60.00 F
19	2		*FRT HEADLAMP LH/RH <i>RH-?/LH-cm</i>	0.00	0.00	*4,700.00 F
20	2		*FRT HEADLAMP LOWER BRACKET LH/RH ?	0.00	0.00	*260.00 F
21	1		*FRT BUMPER LOWER CENTER GARNISH ?	0.00	0.00	*105.00 F

F=Franchise part. S=SpocNett.

Sub Total (\$\$) 10,941.00

+ Margin on L,N Items 10.00% (\$\$) 1,090.60

Total Parts (\$\$) 12,031.60

Sng Ah Tee Motor & Panel Service Pte Ltd/SKF6998U/21/11/2024 14:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS	New	400 600.00
2	TO SPRAY PAINTING ON AFFECTEDS AREAS	New	400 600.00
3	TO CHECK WIRING	New	30 50.00
4	TO DIAGNOSE & RESET FAULT CODE	New	150 280.00
Gross Labour Cost (\$\$)			1,530.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SKF6998U/21/11/2024 14:11. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rose

Hp 9000068

4 days

45

EXCESS: TBA

Revert

Reg after repair

➤ Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

648I

Vehicle Details

Vehicle No.:

SKF6998U

Vehicle to be Exported:

Yes

Intended Deregistration Date:

28 Nov 2024

Vehicle Make:

MERCEDES BENZ

Vehicle Model:

E300 AVG (R18 LED)

Primary Colour:

White

Manufacturing Year:

2019

Engine No.:

26492080016553

Chassis No.:

WDD2130832A728568

Maximum Power Output:

190.0 kW (254 bhp)

Open Market Value:

\$61,824.00

Original Registration Date:

17 Dec 2019

First Registration Date:

17 Dec 2019

Transfer Count:

1

Actual ARF Paid:

\$83,284.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

16 Dec 2029

PARF Rebate Amount:

\$62,463.00

Intended COE Rebate Details

COE Expiry Date:

16 Dec 2029

COE Category:

B - Car above 1600cc or 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$41,805.00

COE Rebate Amount:

\$21,105.00

Total Rebate Amount:

\$83,568.00

Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 19 Nov 2024

OK



Mercedes-Benz E-Class E300 Avantgarde

\$155,800 Instalment \$1,924/mth

Apply for 2.48% loan

Shortlist

Get Warranty



Overview Financial Photo Research

Depreciation	\$24,280 / year
Reg. Date	22-Jul-2019 (4yrs 7mths 24days COE left)
Manufactured	2019
Mileage	91,831 km (17.1k / year)
Transmission	Auto
Engine Cap	1,991 cc
Road Tax	\$1,202 / year
Power	190.0 kW (254 bhp) View specs of the Mercedes-Benz E-Class Saloon 2016 (2016-2021)
Curb Weight	1,670 kg
COE	\$48,010
OMV	\$63,257
ARF	\$85,863
Dereg Value	\$82,425 as of today
No. of Owners	1