

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SGT718A

Vehicle Model : HYUNDAI PDE130N

Chassis Number : TMAHC51ALKJ007097

Estimated Repair Cost

TP Somp
Veron.

S/N	Parts Description	Qty	List Price
1	BONNET <i>new</i>	1	\$ 1857.00 +
2	FRONT BUMPER <i>new</i>	1	\$ 678.00 ✓
3	FRONT BUMPER CLIPS <i>new</i>	10	\$ 50.00 <i>30</i>
4	FRONT BUMPER RETAINER (RHS) <i>new</i> <i>cracked</i>	1	\$ 120.00 + <i>60</i>
5	FRONT BUMPER LOWER LIP <i>new</i>	1	\$ 188.00 ✓
6	FRONT BUMPER TOP RUBBERSTRIP <i>new</i>	1	\$ 110.00 +
7	FRONT RHS FOG LAMP <i>cracked</i>	1	\$ 643.00 <i>455</i>
8	FRONT RHS FOG LAMP COVER <i>new</i>	1	\$ 106.00 ✓
9	RHS HEADLAMP <i>new</i>	1	\$ 3018.00 ✓
10	FRONT RHS FENDER <i>new</i>	1	\$ 2071.00 +
11	FRONT RHS SPLASH SHIELD <i>new</i>	1	\$ 90.00 +
12	FRONT RHS SPLASH SHIELD CLIPS <i>new</i>	10	\$ 50.00 ✓
13	FRONT RHS DOOR <i>new</i>	1	\$ 2138.00 ✓
14	FRONT BUMPER SENSOR <i>new</i>	1	\$ 169.00 +

\$ 11288.00

Discount Less 20%

\$ 2257.60

List Prices Total

\$ 9,030.40

4535
less 20% 3628

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SGT718A

Vehicle Model : HYUNDAI PDE130N

Chassis Number : TMAHC51ALKJ007097

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL FRONT RHS END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD WHERE NECESSARY; TO REPLACE DAMAGED PARTS AS LISTED ABOVE	\$ 1500.00 400
2	TO SPRAY PAINTING ON: BONNET, FRONT BUMPER, FRONT RHS DOOR, FRONT RHS FENDER, FRONT BUMPER LOWER LIP	\$ 1200.00 400
3	TO REMOVE & TRANSFER RHS & FRONT DOOR TRIM BOARD, DOOR SCREEN, POWER WINDOW & ELECTRICAL WIRINGS & SERVICEABLE FITTINGS TO NEW DOOR & TEST FUNCTION.	\$ 400.00 +
4	TO CHECK ELECTRICAL WIRINGS & HEADLIGHTS FUNCTIONS	\$ 150.00 30
5	TO CHECK DIAGNOSE & REMOVE FAULT CODES AFTER ACCIDENT REPAIRS.	\$ 280.00 +
6	TO REMOVE & REPLACE FRONT BUMPER SENSORS & TEST FUNCTION.	\$ 150.00 50
		\$ 3680.00
Parts & Labour Total		\$ 12710.40

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts & Labour Total

Admin C;
1/5 19/12/24

04 Days,

96893735

total: 4508

2/s: 3.6K