

Not Authorized
der
mercus
22/11/24
1/5 @ 14,000/
telephone
10 days

SPEEDWERKZ PRIVATE LIMITED

1 KAKI BUKIT AVENUE 6 #01-73, AUTOBAY, SINGAPORE 417883

Tel: 96195936 / info@speedwerkz.biz

VEHICLE NUMBER: SLN9110R
MAKE & MODEL: HONDA SHUTTLE

BONNET	11		\$980.80	X
BONNET LOCK	11		\$235.40	X
BONNET LOCK BRACKET	cre		\$65.90	✓
FRONT GRILLE CHROME	11		\$302.40	X
FRONT GRILLE BASE	curfere	302.00	\$385.20	✓
FRONT GRILLE EMBLEM	11		\$28.40	✓
HEADLAMP L/R X2	holder cre	2201 X2 = 4402	\$4,500.80	✓
HEADLAMP LOWER BRACKET L/R X2	cre		\$89.40	✓
FRONT BUMPER	DD	1051.20	\$1,250.20	✓
FRONT BUMPER SIDE RETAINER L/R X2	11		\$76.40	X
FRONT BUMPER LOWER GRILLE	1w1		\$178.30	✓
FRONT BUMPER SIDE GRILLE L/R X2	11		\$132.80	X
FRONT BUMPER TOW COVER	R		\$65.40	X
FRONT BUMPER REINFORCEMENT	DD		\$321.60	✓
FRONT BUMPER LOWER COVER	11		\$180.30	X
SUPPORT PANEL	R		\$891.60	X
SUPPORT PANEL TOP GARNISH	11		\$88.70	X
CONDENSER	11		\$1,123.50	X
RADIATOR	11		\$1,540.20	X
TAILGATE	Body DD	1193.20	\$2,101.60	✓
TAILGATE H LOGO	ner		\$52.10	✓
TAILGATE "SHUTTLE" EMBLEM	ner		\$68.30	✓
TAILGATE HINGES L/R X2	11		\$188.80	X
TAILGATE NUMBER PLATE LAMP L/R X2	11		\$146.60	X
TAILGATE OUTER GARNISH	DD		\$342.80	✓
TAILGATE OUTER GARNISH CHROME	cre		\$143.70	✓
TAILGATE SHOCK ABSORBER L/R X2	11		\$416.20	X
TAILGATE LAMP L/R X2	cre	395 X2 = 790	\$996.60	✓
TAILGATE OUTER HANDLE	11		\$241.30	X
TAILGATE INNER HANDLE POCKET	11		\$79.60	X
TAILGATE INNER LOCK	surf/ner		\$218.20	✓
TAILGATE STRIKER	11		\$56.00	X
TAILGATE WEATHERSTRIP	1w1		\$168.70	✓
TAILGATE WINDSCREEN	shortend		\$941.60	✓
TAILGATE WINDSCREEN MOULDING	ner		\$86.30	✓
TAILGATE INNER TRIMBOARD	de/cre		\$379.30	✓
TAILGATE INNER PULL POCKET	11		\$78.90	X
TAILGATE WIPER MOTOR	Damp		\$403.70	✓
TAIL LAMP L/R X2	cre	520.40 X2 = 1040.80	\$1,256.80	✓
REAR BUMPER	DD	936.50	\$1,368.10	✓
REAR BUMPER TOW COVER	1w1	30.00	\$86.30	✓

REAR BUMPER SIDE RETAINER L/R X2	but/cr		\$86.00	✓
REAR BUMPER SIDE BRACKET L/R X2	11		\$79.60	X
REAR BUMPER SPONGE L/R X2	Torn		\$210.80	✓
REAR BUMPER REFLECTORS L/R X2	N/C 11 ok/cr	60.00	\$156.20	1pc
REAR BUMPER REFLECTORS GARNISH L/R X2	11		\$196.80	✓
REAR BUMPER BUZZER	11		\$196.40	X
REAR BUMPER ANTENNA	cr		\$175.80	✓
END PANEL	Body 20	600.80	\$812.70	✓
END PANEL GARNISH	Dis	248.20	\$335.00	✓
REAR FENDER INNER TRIMBOARD L/R X2	De/Torn		\$986.20	✓
FLOOR PANEL	R		\$1,252.30	X
FLOOR PANEL COMPARTMENT TOP COVER	20		\$386.90	✓
FLOOR PANEL COMPARTMENT TRAY SPONGE	Torn		\$305.60	✓
REAR EXHAUST HEAT SHIELD	11		\$89.00	X
REAR floorpanel tray	cr	455.20	\$895.40	✓
REAR EXHAUST RUBBER HANGER X2	11		\$102.00	X
			\$28,525.50	
		Less 20%	\$5,705.10	
			\$22,820.40	

BONNET INSULATOR CLIPS	11		\$80.00	X
1 set FRONT BUMPER CLIPS	11		\$60.00	30
FRONT BUMPER LOWER COVER CLIPS	11		\$60.00	X
FRONT GRILLE CLIPS	11		\$30.00	X
SUPPORT PANEL TOP GARNISH CLIPS	11		\$30.00	X
1 set REAR REVERSE SENSOR	malfunction		\$280.00	200
REAR REVERSE CAMERA	11		\$300.00	X
1 set REAR BUMPER CLIPS	11		\$60.00	30
1 set TAILGATE TRIMBOARD CLIPS	11		\$50.00	30
TAILGATE OUTER GARNISH CLIPS	11		\$30.00	X
TAILGATE WINDSCREEN SOLAR FILM	11		\$350.00	200
TAILGATE WINDSCREEN SEALANT	11		\$100.00	40
TAILGATE WINDSCREEN SPONGE	11		\$60.00	20
END PANEL GARNISH CLIPS	11		\$60.00	X
END PANEL SEALANT	11		\$100.00	40
FLOOR PANEL SEALANT	11		\$100.00	X
REAR NUMBER PLATE WITH GARNISH	Daye		\$70.00	40
			\$1,820.00	

TO CHECK FRONT WIRING AND HEADLAMP LEVELING		\$80.00	30
TO REMOVE & REPLACE CONDENSER, TOP UP A/C GAS	11	\$150.00	X
TO REMOVE & REPLACE RADIATOR, TOP UP COOLANT	11	\$120.00	X
TO CHECK REAR WIRING	rept 1	\$50.00	X
TO REPLACE REAR REVERSE SENSOR		\$80.00	30
TO REMOVE AND REFIT REAR REVERSE CAMERA	11	\$100.00	X
TO REMOVE AND TRANSFER TAILGATE FITTINGS TO NEW		\$100.00	60
TO REMOVE AND REFIT REAR WINDSCREEN		\$180.00	120
TO REMOVE AND REPLACE REAR INTERIOR TRIMS AND GARNISH		\$120.00	60
TO PROVIDE LABOUR, WORKMANSHIP		\$2,400.00	1200
TO SPRAY PAINT ON AFFECTED PANELS		\$2,400.00	1800

RUST PROOFING
TO REMOVE AND REPLACE REAR EXHAUST MUFFLER

\$150.00 80
11 \$150.00 x
\$6,080.00

Total

\$30,720.40

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 16946-30

202

13557.04

630

3380

17567.04

22%

14051