



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24110488/Uvp3e2
50 RAFFLES PLACE #03-03	Date:	30/12/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SME 440H	Veh. Inspected	SGP 8199R
Policy No.	D24MTPV01009881	Coverage	0
Claim No.	CMTD2403661/JYC	Excess	\$0.00
Assign From	GRACE TEO	Assign Date	22/11/2024

2. Vehicle Details

Make & Model	MAZDA 3 (A)	C.C	1496
Engine No.	P520377381	Year of Reg.	24/11/2016
Chassis No.	JM6BM42A8G0347351	Colour	RED
Odometer	117512 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/60R16	YOKOHAMA	6
L/H Front Tyre	205/60R16	YOKOHAMA	6
R/H Rear Tyre	205/60R16	YOKOHAMA	6
L/H Rear Tyre	205/60R16	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/11/2024	Inspection Date	25/11/2024
Survey held at	AUTO EUROKARS PTE LTD 5 UBI CLOSE, SINGAPORE 408605		

5a. Remarks

A) THE VEHICLE HAS NOT SEND IN FOR REPAIRS..
B) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days