

## QUOTATION

CODE: F0001  
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
 ADDRESS: 16 RAFFLES QUAY  
 #42-01  
 HONG LEONG BUILDING  
 SINGAPORE 048581  
 ATTN: MOTOR CLAIM DEPT  
 CONTACT NO.: 65073846  
 MODEL: Porsche Cayman GTS PDK  
 CHASSIS NO.: WP0ZZZ98ZFK182868  
 ENGINE NO.: EF06403  
 REG NO.: SND7700E  
 REGN DATE: 12/08/2015

PAGE NO.: 1  
 DOCUMENT NO.: 721  
 DOCUMENT DATE: 21/11/2024  
 POS ID: ES  
 PRINTED BY: Muhammad Nur Faiz  
 SERVICE ADV: Muhammad Nur Faiz  
 CSP/OP CODE: W  
 DEPT: 31836  
 WIP NO.: DS/SND7700E/0371  
 REF. NO.:  
 DATE IN:  
 EXT. WTY:  
 MILEAGE: 0

DESCRIPTION: Body & Upholstery

| Item               | Description                                                                                                                       | Qty.     | Unit Price | Stk/Status | Gross amount | GST Code |
|--------------------|-----------------------------------------------------------------------------------------------------------------------------------|----------|------------|------------|--------------|----------|
|                    |                                                                                                                                   |          | SGD        |            | SGD          |          |
| NOTES              | TP CLAIM - FIRST CAPITAL                                                                                                          | 0.00     | 0.00       |            | 0.00         | O        |
| INS-PB-(L)         | TO REMOVE /REPLACE FRONT BUMPER, FRONT FENDER RH & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. | 5,160.00 | 1.00       | 2580 /     | 5,160.00     | S        |
| INS-PAINT-(L)      | TO RESPRAY FRONT BUMPER, FRONT FENDER RH.                                                                                         | 2,800.00 | 1.00       | 2600 /     | 2,800.00     | S        |
| INS-PB-(L)         | TO CARRY-OUT BODY CAVITY PRESERVATION.                                                                                            | 250.00   | 1.00       | 150 /      | 250.00       | S        |
| INS-PB-(L)         | TO REMOVE & REPLACE TURBO COOLER, RADIATOR, CONDENSER AND RADIATOR FAN ASSY.                                                      | 1,720.00 | 1.00       | X ?        | 1,720.00     | S        |
| INS-PB-(L)         | TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.                                                   | 500.00   | 1.00       | X ?        | 500.00       | S        |
| INS-PB-(L)         | TO TRANSFER THE FRONT BUMPER SENSORS.                                                                                             | 500.00   | 1.00       | 250 /      | 500.00       | S        |
| INS-PB-(L)         | TO SUPPLY & INSTALL THE BODY WRAP STICKER ON AFFECTED AREAS. (PRICE TO BE ADVISE)                                                 | 1.00     | 1.00       | X ?        | 1.00         | S        |
| INS-PB-(L)         | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.                                                                                | 250.00   | 1.00       | 150 /      | 250.00       | S        |
| INS-PB-(L)         | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.                                                                                   | 600.00   | 1.00       | 1 /        | 600.00       | S        |
| INS-PB-(L)         | SUNDRIES.                                                                                                                         | 50.00    | 1.00       | 20 /       | 50.00        | S        |
| 981-505-011-73-    | FRONTBUMPER                                                                                                                       | 1.00     | 2,507.10   |            | 2,507.10     | S        |
| 981-505-525-13-OK1 | FRONT BUMPER LOWER SPOILER                                                                                                        | 1.00     | 868.70     |            | 868.70       | S        |
| 981-505-564-03-OK1 | RETAINING FRAME RH                                                                                                                | 1.00     | 142.80     |            | 142.80       | S        |

stere (LKK)  
 20/11/24, 11.30am  
 without Prejudice  
 P/P, Resurvey Before Spray, 4 days

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of S180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

\*This estimate is valid for a period of thirty (30) days only.

\*Prices are subject to change without prior notice.

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Eurokars Aftersales Centre  
 Acknowledged by Repairer  
 27A Tanjong Penjuru, Level 5  
 Signature: Singapore 609042  
 Date:

Co. Regn. No. 198602110Z  
 GST Regn. No. M90364005A

Tel: (65) 6331 0680  
 Fax: (65) 6331 0690  
 Website: www.eurokarsservices.com.sg

## QUOTATION

CODE: F0001  
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
 ADDRESS: 16 RAFFLES QUAY  
 #42-01  
 HONG LEONG BUILDING  
 SINGAPORE 048581  
 ATTN: MOTOR CLAIM DEPT  
 CONTACT NO.: 65073846  
 MODEL: Porsche Cayman GTS PDK  
 CHASSIS NO.: WP0ZZZ98ZFK182868  
 ENGINE NO.: EF06403  
 REG NO.: SND7700E  
 REGN DATE: 12/08/2015

PAGE NO.: 2  
 DOCUMENT NO.: 721  
 DOCUMENT DATE: 21/11/2024  
 POS ID: ES  
 PRINTED BY: Muhammad Nur Faiz  
 SERVICE ADV: Muhammad Nur Faiz  
 CSP/OP CODE: W  
 DEPT: 31836  
 WIP NO.: DS/SND7700E/0371  
 REF. NO.:  
 DATE IN:  
 EXT. WTY:  
 MILEAGE: 0

DESCRIPTION: Body & Upholstery

| Item               | Description                       | Qty. | Unit Price | Stk/Status | Gross GST |      |
|--------------------|-----------------------------------|------|------------|------------|-----------|------|
|                    |                                   |      |            |            | amount    | Code |
|                    |                                   |      | SGD        |            | SGD       |      |
| 981-505-794-01-    | STRUT BRACE X nn                  | 1.00 | 173.20     |            | 173.20    | S    |
| 981-505-654-03-OK1 | SENSOR COVER RH ✓ CHT             | 1.00 | 214.00     |            | 214.00    | / S  |
| 981-606-193-00-OK1 | SENSOR X nn                       | 1.00 | 360.90     |            | 360.90    | S    |
| 7PP-919-133- -     | SENSOR GASKET ✓ nec               | 4.00 | 6.70       |            | 26.80     | / S  |
| 992-807-891- -     | FIXING DEVICE ✓ nec               | 2.00 | 30.20      |            | 60.40     | / S  |
| 981-505-536-00-    | FRONT BUMPER RETAINER RH ? x nn   | 1.00 | 30.30      |            | 30.30     | S    |
| 999-190-191-30-    | Blind rivet ✓ nec                 | 6.00 | 8.10       |            | 48.60     | / S  |
| 999-591-941-40-    | Expansion rivet ✓ nec             | 6.00 | 3.10       |            | 18.60     | / S  |
| 981-505-707-00-    | BRACKET SPACER ? x nn             | 2.00 | 27.90      |            | 55.80     | S    |
| 981-505-761-02-    | RETAINER PLATE HEADLIGHT LH ✓ nec | 1.00 | 77.20      |            | 77.20     | / S  |
| 981-505-762-02-    | RETAINER PLATE HEADLIGHT RH ✓ nec | 1.00 | 77.20      |            | 77.20     | / S  |
| 981-503-032-00-GRV | FRONT FENDER RH ✓ DD              | 1.00 | 1,966.80   |            | 1,966.80  | / S  |
| 991-503-555-00-    | BRACKET HEADLIGHT RH X nn         | 1.00 | 35.50      |            | 35.50     | S    |
| 991-503-558-00-    | FENDER BRACKET RH X nn            | 1.00 | 34.30      |            | 34.30     | S    |
| 991-503-441-01-    | FENDER STRUT BRACE RH X nn        | 1.00 | 51.40      |            | 51.40     | S    |
| 981-575-322-04-1E0 | AIR GUIDE CONDENSER RH ? x nn     | 1.00 | 129.40     |            | 129.40    | S    |
| 991-573-111-06-    | CONDENSER RH ? x nn               | 1.00 | 944.20     |            | 944.20    | S    |
| 991-573-711-02-    | SEALING FRAME RH ? x nn           | 1.00 | 89.00      |            | 89.00     | S    |
| 991-106-132-03-    | RADIATOR RH ? x nn                | 1.00 | 2,090.30   |            | 2,090.30  | S    |
| 981-624-935-01-    | RADIATOR FAN RH ? x nn            | 1.00 | 1,125.90   |            | 1,125.90  | S    |

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

\*This estimate is valid for a period of thirty (30) days only.

\*Prices are subject to change without prior notice.

## QUOTATION

CODE: F0001  
 CUSTOMER: MS FIRST CAPITAL INSURANCE LTD  
 ADDRESS: 16 RAFFLES QUAY  
 #42-01  
 HONG LEONG BUILDING  
 SINGAPORE 048581  
 ATTN: MOTOR CLAIM DEPT  
 CONTACT NO.: 65073846  
 MODEL: Porsche Cayman GTS PDK  
 CHASSIS NO.: WP0ZZZ98ZFK182868  
 ENGINE NO.: EF06403  
 REG NO.: SND7700E  
 REGN DATE: 12/08/2015

PAGE NO.: 3  
 DOCUMENT NO.: 721  
 DOCUMENT DATE: 21/11/2024  
 POS ID: ES  
 PRINTED BY: Muhammad Nur Faiz  
 SERVICE ADV: Muhammad Nur Faiz  
 CSP/OP CODE: W  
 DEPT: 31836  
 WIP NO.: DS/SND7700E/0371  
 REF. NO.:  
 DATE IN:  
 EXT. WTY:  
 MILEAGE: 0

DESCRIPTION: Body & Upholstery

| Item            | Description                    | Qty. | Unit Price | Stk/Status | Gross GST amount Code |
|-----------------|--------------------------------|------|------------|------------|-----------------------|
|                 |                                |      | SGD        |            | SGD                   |
| 991-106-156-02- | RADIATOR FAN BRACKET RH ? x nn | 1.00 | 546.10     |            | 546.10 S              |
| 991-106-342-00- | AIR GUIDE RADIATOR RH ? x nn   | 1.00 | 101.20     |            | 101.20 S              |
| 991-106-766-02- | VENT LINE RH ? x nn            | 1.00 | 118.70     |            | 118.70 S              |
| 000-043-305-15- | ANTIFREEZE COOLANT ? x nn      | 6.00 | 44.70      |            | 268.20 S              |
| 981-631-264-03- | HEADLIGHT RH x nn              | 1.00 | 5,906.20   |            | 5,906.20 S            |
| 981-631-188-01- | ADDITIONAL HEADLIGHT RH x nn   | 1.00 | 643.30     |            | 643.30 S              |
| 991-631-156-03- | SIGNAL LIGHT RH / BR           | 1.00 | 92.90      |            | 92.90 / S             |

|           | *         | GST Code | Rate  | Service/Goods | GST      | Before GST       | GST       | Total    |           |
|-----------|-----------|----------|-------|---------------|----------|------------------|-----------|----------|-----------|
| Parts     | 18,805.00 | O        | -     |               | -        | Gross *          | 30,636.00 | 2,757.24 | 33,393.24 |
| Surcharge | 0.00      | S        | 9.00% | 30,636.00     | 2,757.24 | Less: Deposit ** | 0.00      | 0.00     | 0.00      |
| Labour    | 11,831.00 |          |       |               |          | Amount Due       | 30,636.00 | 2,757.24 | 33,393.24 |
| Menus     | 0.00      |          |       |               |          |                  |           |          |           |
|           |           |          |       |               |          |                  |           |          |           |

\*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

\*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

\*\* Deposit tax invoice No.:

\*This estimate is valid for a period of thirty (30) days only.

\*Prices are subject to change without prior notice.

**Eurokars Services Pte Ltd**

Date:

Customer signature

Authorised signature

Co. Regn. No. 198602110Z  
 GST Regn. No. M90364005A

Eurokars Aftersales Centre  
 27A Tanjong Penjuru, Level 5  
 Singapore 609042

Tel: (65) 6331 0680  
 Fax: (65) 6331 0690  
 Website: www.eurokarsservices.com.sg