


**PHOTOGRAPHS FOR VEHICLE NO. : SHC 5591S**



**PHOTOGRAPHS FOR VEHICLE NO. : SHC 5591S**





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

INSPECTION PHOTOS (Page 3 of 4)

### PHOTOGRAPHS FOR VEHICLE NO. : SHC 5591S





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.

19-9607198-R

INSPECTION PHOTOS (Page 4 of 4)

### PHOTOGRAPHS FOR VEHICLE NO. : SHC 5591S

