



PROGRESSIVE
CAR CARE PTE LTD

Progressive Car Care Pte Ltd

(Co. Reg. No. 201006949C)

Blk 3022A Ubi Road 1 #01-45/ 46 S408716

T: +65 6741 5336 | F: +65 6741 7208

E: claims@procarcare.com.sg

W: www.procarcare.com.sg

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD 1124-10375
Policy No:	MPC23P00300000	Date of Loss:	13/11/2024
Vehicle Reg. No.:	SLU279K	Driveable?	
Driver Age/Info:	39 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LOH CHOON KIAT	Contact No:	+6593387948
Driver:	LOH CHOON KIAT		
Make/Model:	HYUNDAI ACCENT (RB), 1.4 CVT (A)	Vehicle Reg. Date:	20/11/2017
Vehicle Colour:	BLACK	Chassis No:	KMHCU41BTJU388865
Engine No:	G4LCHU873544		
Odometer:	141258 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	8 4		

Present Location: PROGRESSIVE CAR CARE PTE LTD (HQ)

COST OF CLAIMS

	Amount
Parts	842.60
Miscellaneous Items	0.00
Labour	790.00
Paintwork Labour	1,000.00
Towing	0.00
Gross Total (\$\$)	2,632.60
+ GST 9.00% (\$\$)	236.93
Nett Amount (\$\$)	2,869.53

This claim is handled by: LIANG SIEW CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

not Authorized
on
money
Excess \$500
26/11/24
when 26/11/24
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 22 Nov 2024)

Parts: 143

HYUNDAI ACCENT (RB) 1.4 CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Progressive Car Care Pte Ltd/SLU279K/22/11/2024 16:38

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*REAR BUMPER	0.00	0.00	480.00 F ✓
2	2	NA	*REAR BUMPER SIDE RETAINER - LH/RH	0.00	0.00	46.00 F X
3	10	NA	*REAR BUMPER CLIPS	0.00	0.00	18.00 F ✓
4	1	NA	*REAR BUMPER REFLECTOR - LH	0.00	0.00	32.00 F ✓
5	1	NA	*TAILLAMP - LH	0.00	0.00	190.00 F ✓
Sub Total (\$\$)						766.00
+ Margin on L,N Items 10.00% (\$\$)						76.60
Total Parts (\$\$)						842.60

F=Franchise part.

Progressive Car Care Pte Ltd/SLU279K/22/11/2024 16:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New 800	1,000.00
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS ON 2 DOORS LH; REAR FENDER LH, REMOVE, REPLACE ACCIDENT PORTIONS	New 330	770.00
3	TO CHECK WIRING	New	20.00
Gross Labour Cost (\$\$)			1,790.00

Progressive Car Care Pte Ltd/SLU279K/22/11/2024 16:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.