

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Vonn Siow Lie Mien

Date: 09 Dec 2024

Preliminary Advice

Insured Vehicle No	: SLZ7183E	Accident Date	: 21/11/2024
TP Vehicle No	: SNP5025X	Assignment Date	: 25/11/2024
Make	: TOYOTA VOXY HYBRID	Est. Duration of Repair	: 5
Date of Inspection	: 25/11/2024		
Inspection At	: RC AUTO-160 SIN MING (HQ) 160 SIN MING DRIVE, #06-20 SIN MING AUTOCITY SINGAPORE 575722		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,855.37
Revised Amount	:S\$	4,909.98
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,909.98

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- ☐ The vehicle is economical for repair
- ☐ The vehicle is not economical for repair
- ☒ Part-by-Part repair
- ☐ Lump Sum repair

- ☒ The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.