



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMZ 1623E

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NOT NECESSARY	\$100.00	\$0.00
1	BUMPER FRONT (SN)	TO REPAIR SEE LABOUR	\$1,022.00	\$0.00
10	BUMPER CLIPS (SN)	NOT NECESSARY	\$70.00	\$0.00
1	FENDER LINER FRONT LH (SN)	NOT NECESSARY	\$196.00	\$0.00
10	FENDER LINER CLIPS (SN)	NOT NECESSARY	\$70.00	\$0.00
1	DAYTIME RUN LAMP FRONT LH (SN)	BROKEN	\$406.00	\$406.00
1	DAYTIME RUN LAMP TRIM FRONT LH (CHROME) (SN)	NOT NECESSARY	\$91.00	\$0.00
1	ENGINE UNDERCOVER CENTRE (SN)	NOT NECESSARY	\$1,239.00	\$0.00
1	BUMPER FRONT UNDERCOVER (SN)	NOT NECESSARY	\$154.00	\$0.00
1	SET SENSOR BRACKET FRONT (SN)	NOT NECESSARY	\$200.00	\$0.00
			\$3,548.00	\$406.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE & REPLACE BUMPER FRONT, FENDER LINER FRONT LH, DAYTIME RUN LAMP FRONT LH, ENGINE UNDERCOVER CENTRE, BUMPER FRONT UNDERCOVER & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF BUMPER FRONT		\$500.00	\$150.00
	TO SPRAY BUMPER FRONT		\$300.00	\$200.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING		\$100.00	\$30.00
	TO PROGRAMME AFTER THE ACCIDENT REPAIR WORKS	NOT NECESSARY	\$150.00	\$0.00
	TO CARRY OUT BODY CAVITY PRESERVATION	NOT NECESSARY	\$150.00	\$0.00
			\$1,200.00	\$380.00

<b>GRAND TOTAL</b>			<b>\$4,748.00</b>	<b>\$786.00</b>
	<b>RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE)</b>			<b>\$786.00</b>

Report Ref No: CS/FCI24110511/Enp3e2

MARKET VALUE: \$95,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$71,652.00=NETT VALUE: \$23,348.00

**CTY**

STEVE CHEN TSUE YEE



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.