

SQM PTE LTD
HANDPHONE 90030857

Date : 25 Nov 2024

SOMPO INSURANCE

DATE ACCIDENT : 18 Nov 2024

QUOTATION - THIRD PARTY CLAIM

CLAIM : THIRD PARTY CLAIM

VEH. No SNJ 3867 C / HARRIER

INSURE : INCOME

ATTN : MOTOR CLAIM DEPARTMENT

QTY	ITEM	AMOUNT	
1	TAILGATE <i>1802-20</i>	\$ <i>B</i> 3,220.00	✓
1	TAILGATE HARRIER EMBLEM <i>68</i>	\$ <i>nc</i> 140.00	✓
1	TAILGATE HYBRID EMBLEM <i>98-80</i>	\$ <i>nc</i> 140.00	✓
1	TAILGATE WEATHERSTRIP <i>357</i>	\$ <i>pd 101-1</i> 485.00	✓
1	TAILGATE LOCK LOWER SENSOR	\$ <i>sn</i> 580.00	X
1	REAR W/SCREEN MOULDING <i>121</i>	\$ <i>nc</i> 298.00	✓
1	REAR BUMPER <i>865</i>	\$ <i>Bu</i> 1,895.00	✓
2	REAR BUMPER SENSORS	\$ <i>shon</i> 960.00	✓
2	REAR BUMPER SENSOR BRACKETS	\$ <i>nn</i> 448.00	X
1SET	REAR BUMPER SENSOR CABLE	\$ <i>cn</i> 587.00	✓
1	REAR BUMPER SPONGE	\$ <i>sn</i> 620.00	X
1	REAR BUMPER REINFORCEMENT <i>627</i>	\$ <i>B</i> 785.00	✓
12	REAR BUMPER BRACKETS	\$ <i>R</i> 440.00	X
2	REAR BUMPER RETAINERS	\$ <i>sn</i> 280.00	X
1	REAR BUMPER CENTER CHROME <i>361</i>	\$ <i>cm</i> 685.00	✓
2	REAR BUMPER SIDE CHROMES <i>0241</i>	\$ <i>ms cm</i> 798.00	✓
2	REAR BUMPER REFLECTORS	\$ <i>sn</i> 1,560.00	X
1	REAR BUMPER LOWER GARNISH <i>506</i>	\$ <i>B</i> 980.00	✓
1	REAR EXHAUST	\$ <i>R</i> 1,585.00	X
1	END PANEL	\$ <i>R</i> 985.00	X
1	END PANEL TOP GARNISH <i>468-90</i>	\$ <i>ms cm</i> 580.00	✓
TOTAL PARTS :		\$ 18,051.00	
LESS 25%		\$ 4,512.75	
TOTAL LIST PARTS :		\$ 13,538.25	
<u>S/NETT PARTS</u>			
2	REAR W/SCREEN SEALANT	\$ <i>nc</i> 140.00	✓
10	REAR BUMPER CLIPS	\$ <i>nc</i> 45.00	✓
TOTAL S/N :		\$ 185.00	
TOTAL PARTS PRICE :		\$ 13,538.25	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AMOUNT BRING FORWARD :		\$	13,538.25	
Labour to do repair, replace align adjust on accident area	\$	1,600.00		500
To transfer tailgate parts to another tailgate	\$	140.00		60
To replace rear exhaust	\$	~ 180.00		X
To do anti rust	\$	120.00		30
To do sealant, seal gap, waterproofing on accident affected area	\$	250.00		20
To remove refix replace garnish, side trim upholstery etc	\$	280.00		40
To check wiring system replace sensors, cable , etc	\$	200.00		60
To do spray painting on accident area inner outer	\$	1,000.00		600
TOTAL LABOUR :		\$	3,770.00	
GRAND TOTAL PARTS AND LABOUR :			\$	17,308.25

SQM PTE LTD
HANDPHONE 90030857
SUPPLEMENTARY PARTS

Date : 25 Nov 2024

QUOTATION - THIRD PARTY CLAIM

SOMPO INSURANCE

CLAIM : THIRD PARTY CLAIM

DATE ACCIDENT : 18 Nov 2024

VEH. No SNJ 3867 C / HARRIER

ATTN : MOTOR CLAIM DEPARTMENT

INSURE : INCOME

QTY	ITEM	AMOUNT	
4	REAR BUMPER SENSOR HOLDER/ BRACKETS	\$ <i>R</i> 720.00	<i>X</i>
1	REAR KICK SENSOR <i>710.40</i>	\$ <i>nd</i> 985.60	<i>✓</i>
1	REAR KICK SENSOR HOLDER ASSY <i>728.10</i>	\$ <i>h</i> 845.80	<i>✓</i>
TOTAL PARTS :		\$ 2,551.40	
LESS 25%		\$ 637.85	
TOTAL LIST PARTS :		\$ 1,913.55	
TOTAL SUPPLEMENTARY PARTS :		\$ 1,913.55	

AMOUNT BRING FORWARD :	\$ 1,913.55	
TO RESET, diagnose , programme for rear auto tailgate, kick sensor , blind soif sensor etc after repair	\$ 380.00	<i>1201</i>
TOTAL LABOUR :	\$ 380.00	
GRAND TOTAL PARTS AND LABOUR :	\$	2,293.55