

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6744 4986

Reg. No: 201427944N

Email: MG3SOLUTION@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	27/11/2024
CLAIM TYPE:	T/P CLAIM
TO:	LONPAC
VEHICLE DETAILS	
VEHICLE NO:	SLS303J
MAKE & MODEL:	TOYOTA HARRIER G GRADE
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	11 November, 2024
TIME:	1700HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR DOOR LH <i>Dented</i>	1	\$ 1,850.00	\$ 1,850.00
TOTAL PRICE				\$ 1,850.00
LESS 25%				\$ 462.50
SUB TOTAL PRICE				\$ 1,387.50

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 400.00	\$ 400.00
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 400.00	\$ 400.00
3	TUFF COAT	1	\$ 200.00	\$ 200.00
4	WIRING CHECK	1	\$ 80.00	\$ 80.00
8	TRANSFER REAR DOOR MECHANISM	1	\$ 100.00	\$ 100.00

TOTAL \$ 1,180.00

ESTIMATE REPORT

TOTAL PARTS COST	\$	1,387.50
TOTAL LABOUR COST	\$	1,180.00
TOTAL REPAIR COST	\$	2,567.50

APPROVED DETAILS:

SURVEYOR:

CONTACT NO.:
PART BY PART/LUMP SUM
NO. OF DAYS

Adnan Lj
P/P ~~27/11/24~~
03 Days

blnd: 15/6225062250
(P/P)

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: