

ONE GARAGE PTE LTD

8 KAKI BUKIT AVENUE 4 #03-33 PREMIER@KAKI BUKIT

SINGAPORE 415875

TEL: 96311088

TO	: LIBERTY	DATE	: 27/11/2024
VEHICLE NO	: SNG8964M (2008)		
VEHICLE MODEL	: HONDA CIVIC TYPE R		Xiao Chen
CHASSIS NO	: FD21401846		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER <i>Repairs</i>	1	\$ 1,101.40	\$ 1,101.40
2	FRONT BUMPER SIDE HOLDER <i>NEW</i>	1	\$ 36.50	\$ 36.50
3	FRONT FENDER <i>Repairs</i>	1	\$ 789.90	\$ 789.90
4	HEADLAMP NEW x nn	1	\$ 1,298.10	\$ 1,298.10
5	FRONT WING MIRROR <i>Cracked</i>	1	\$ 682.70	\$ 682.70
6	FRONT DOOR <i>Repairs</i>	1	\$ 1,042.50	\$ 1,042.50
7	FRONT DOOR HANDLE <i>Repairs</i>	1	\$ 189.50	\$ 189.50

TOTAL PRICE: \$ 5,140.60

LESS 20% \$ 1,028.12

SUB TOTAL PRICE: \$ 4,112.48

1980.80

1584.64

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER CLIPS <i>NEW</i>	1 SET	\$ 30.00	\$ 30.00
2	FRONT BUMPER LOWER SPOILER <i>Repairs</i>	1	\$ 1,400.00	\$ 1,400.00
3	FRONT DOOR VISOR <i>NEW</i>	1	\$ 100.00	\$ 100.00
4	FRONT DOOR BLACK TAPE <i>NEW</i>	1 SET	\$ 60.00	\$ 60.00

TOTAL : \$ 1,590.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS 100	\$ 1,000.00	300	
2	SPRAY PAINTING TO AFFECTED AREA 100	\$ 2,000.00	1000	
3	WIRING CHECK	\$ 50.00	30 X	
6	TO TRANSFER FRONT DOOR FITTINGS	\$ 150.00	X	
7	TO APPLY TUFF COAT	\$ 150.00	30 X	

TOTAL: \$ 3,350.00

1360

ESTIMATE REPORT

TOTAL PARTS COST: \$ 5,702.48

TOTAL LABOUR COST: \$ 3,350.00

TOTAL REPAIR COST: \$ 9,052.48

total: 2944.64

h/s: 2.3K. ✓

0.4 days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: