

BLUWEL AUTOMOTIVE SERVICE PTE LTD  
 1 KAKI BUKIT AVE 6 # 01-28/53/55/56  
 SINGAPORE 417883 TEL :67452088

*No + Authorized  
 de  
 mens  
 2/12/24  
 2/s \$1800/  
 complete repair*

*4 days*

VEHICLE No: SKG 1853G

1PC	REAR BUMPER		\$749.00	✓
1PC	REAR BUMPER LOWER	<i>Re/Torn grate</i>	\$241.00	✓
1PC	REAR BUMPER BEAM	<i>n1</i>	\$318.00	X
1PC	REAR BUMPER REFLECTOR N/S	<i>one</i>	\$68.00	✓
1PC	REAR BUMPER SIDE RETAINER N/S	<i>one</i>	\$65.00	✓
1SET	REAR BUMPER CLIPS	<i>new</i>	\$50.00	✓
1PC	REAR END PANEL	<i>R</i>	\$608.00	X
1PC	TAILLAMP N/S	<i>n1</i>	\$520.00	X
1PC	REAR FENDER N/S	<i>R</i>	\$1,197.00	X
1PC	REAR FENDER UNDER SHIELD N/S	<i>n1</i>	\$118.00	X
			\$3,934.00	
			LESS 25%	\$3,540.60

S.NETT

1SET	REAR BUMPER REVERSE SENSOR	<i>su</i>	\$280.00	X
1PC	REAR END PANEL SEALANT	<i>n1</i>	\$50.00	X
1SET	REAR FENDER STICKER N/S	<i>new</i>	\$250.00	100

TO CHECK WIRING	\$50.00	20
TO DISMANTLE & REPLACED REVERSE SENSOR	\$80.00	30
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	60
TO SPRAY RUST PROOFING	\$100.00	X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,000.00	400
TO PUTTY & SPRAY PAINTING	\$1,000.00	600
TOTAL	\$6,470.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) to the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*1-1173  
 102  
 1055.70  
 100  
 1110  
 2265.70  
 202  
 182*