

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6744 4986

Reg. No: 201427944N

Email: MG3SOLUTION@GMAIL.COM

Xiao Chen

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	02-12-24
CLAIM TYPE:	T/P CLAIM
TO:	INCOME
VEHICLE DETAILS	
VEHICLE NO:	SMD8065K
MAKE & MODEL:	HONDA FREED HYBRID 1.5
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	9 November, 2024
TIME:	1540HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	ROCKER PANEL <i>Dented</i>	1	\$ 860.00	\$ 860.00
2	FRONT DOOR <i>Dented</i>	1	\$ 1,550.30	\$ 1,550.30
3	FRONT DOOR LOCK <i>New</i>	1	\$ 320.00	\$ 320.00
4	FRONT DOOR POWER WINDOW REGULATION <i>2nd</i>	1	\$ 230.00	\$ 230.00
5	FRONT DOOR POWER WINDOW REGULATION MOTOR <i>2nd</i>	1	\$ 420.00	\$ 420.00
6	FRONT DOOR INNER TRIM BOARD <i>2nd</i>	1	\$ 920.00	\$ 920.00
7	REAR SLIDING DOOR <i>Dented</i>	1	\$ 1,855.30	\$ 1,855.30
8	REAR SLIDING DOOR RUBBER <i>1st</i>	1	\$ 110.00	\$ 110.00
9	REAR SLIDING DOOR LOCK <i>New</i>	1	\$ 350.00	\$ 350.00
10	REAR DOOR POWER WINDOW REGULATION <i>New</i>	1	\$ 380.00	\$ 380.00
11	REAR DOOR POWER WINDOW REGULATION MOTOR <i>New</i>	1	\$ 420.00	\$ 420.00
12	DOOR CENTRE PILLAR <i>Repair</i>	1	\$ 1,155.30	\$ 1,155.30

TOTAL PRICE \$ 8,570.90

LESS 25% \$ 2,142.73

SUB TOTAL PRICE \$ 6,428.18

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT DOOR INNER TRIM BOARD CLIPS(SET) <i>New</i>	1	\$ 20.00	\$ 20.00
2	SUN BLADE <i>New</i>	1	\$ 150.00	\$ 150.00

TOTAL \$ 170.00

1310

685

1640

4835
3868

140

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,400.00	\$ 1,400.00	8w
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,400.00	\$ 1,400.00	8w
3	TUFF COAT	1	\$ 280.00	\$ 280.00	60
4	WIRING CHECK	1	\$ 100.00	\$ 100.00	30
5	TO REMOVE AND REFIX FRONT DOOR MECHANISM	1	\$ 100.00	\$ 100.00	60
6	TO REMOVE AND REFIX REAR DOOR MECHANISM	1	\$ 100.00	\$ 100.00	60

TOTAL \$ 3,380.00

1810

ESTIMATE REPORT

TOTAL PARTS COST	\$	6,598.18
TOTAL LABOUR COST	\$	3,380.00
TOTAL REPAIR COST	\$	9,978.18

APPROVED DETAILS:

SURVEYOR:

CONTACT NO.:

PART BY PART/LUMP SUM

NO. OF DAYS

Adrian G
1/s 02/12/24.

86 days.

total: 5818

L/s: 4.61K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: