



ESTIMATE

Account Details			Account No.		Customer Details		
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICCI1		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925		
			Document No. 0				
			Document Date 25/11/2024				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	28/06/2017	SLQ1172Z	0	34952	67/DS/SLQ1172Z
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU103561319		2ZRS056117	60	Sam San Joi	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP-XE9029Z ACC DATE:24/11/2024 TOW IN:24/11/2024 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 100.00	
2	B	BP-LAB2 CHECK LIGHTING & WIRING SYSTEM				Xm? 198.00	
3	B	BP-MECH2 REMOVE & INSTALL AIRCON CONDENSER ASSY A ND CHARGE UP GAS				Xm? 198.00	
4	Z	BP-SLANT SUPPLY SEALANT (NETT)				Xm? 200.00	
5	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				198.00	
6	B	BP-LAB2 REPLACE FRT ACCIDENT DAMAGED PARTS STRAIGHTEN & ALIGN FRT ACCIDENT AFFECTED AREAS				1584 3960.00	
7	B	BP-RES2 RESPRAY JOB ON FRT ACCIDENT AFFECTED ARE AS				1312 3280.00	
8	1	U52119-47962 COVER, FR BUMPER	1.00	799.30		799.30	
9	2	U53395-47040 SEAL, HOOD TO FR END	1.00	71.50		71.50	
10	3	U52116-47050 SUPPORT, FR BUMPER	1.00	121.30		121.30	
11	4	U52115-47050 SUPPORT, FR BUMPER	1.00	121.30		121.30	
12	5	K52161-0K040 PIECE, RR BUMPER	10.00	5.80		58.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925	
Document No. 0		Document Date 25/11/2024		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q3	28/06/2017	SLQ1172Z	0	34952	67/DS/SLQ1172Z

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKB3FU103561319	2ZRS056117	60	Sam San Joi	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	6	U52611-47140 ABSORBER, FR BUMPER <i>7.5x1</i>	1.00	110.20		110.20
14	7	U52021-47110 REINFORCEMENT <i>4.5x1</i>	1.00	1105.80		1105.80
15	8	U53101-47081 GRILLE SUB-ASSY <i>con</i>	1.00	484.10		484.10
16	9	U53301-47110 HOOD SUB-ASSY <i>repair</i>	1.00	1380.00		1380.00
17	0	U53802-47100 FENDER SUB-ASSY, FR <i>Xan</i>	1.00	1488.90		1488.90
18	1	U75310-47060 EMBLEM ASSY, <i>Xan</i>	1.00	126.10		126.10
19	2	U75374-47150 EMBLEM, SIDE PANEL <i>Xan</i>	1.00	75.70		75.70
20	3	U53510-47140 LOCK ASSY, HOOD <i>7.5x1</i>	1.00	187.20		187.20
21	4	U53217-47030 BRACE, HOOD LOCK <i>7.5x1</i>	1.00	107.80		107.80
22	5	U53205-47900 SUPPORT S/A, <i>7.5x1</i>	1.00	522.80		522.80
23	6	U53214-47050 SUPPORT, RADIATOR, <i>7.5x1</i>	1.00	109.40		109.40
24	7	U53213-47050 SUPPORT, RADIATOR, <i>7.5x1</i>	1.00	109.40		109.40
25	8	U81185-47691 UNIT, HEADLAMP <i>con</i>	1.00	4063.00		4063.00
26	9	U81145-47691 UNIT, HEADLAMP <i>7.5x1</i>	1.00	4063.00		4063.00
27	0	U88460-10320 CONDENSER ASSY <i>7.5x1</i>	1.00	2462.90		2462.90
28	1	U16400-37311 RADIATOR ASSY <i>7.5x1</i>	1.00	3067.40		3067.40
29	2	U16711-37160 SHROUD, FAN <i>7.5x1</i>	1.00	366.90		366.90
30	3	S08889-80102 COOLANT, SLLC&& <i>7.5x1</i>	1.00	108.00		108.00

KK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature: _____

Date: _____

For & on behalf of the Repairer of the following:		Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Customer's Signature		29,244.00
		Parts 21,110.00	
		Labour 8,134.00	
		Sublet 0.00	
		Lubrication/Fluid 0.00	
		Others 0.00	
		GST 9.00%	2,631.96
		Less	0.00
		Amount Due	31,875.96

Company Copy



Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-S

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details																														
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept			S1000003 / ICC11		M/S Grab Rentals Pte. Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925																														
			Document No.																																
			0																																
			Document Date																																
			04/12/2024																																
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks																												
2017	ZVW50R	AHXEBW Q3	28/06/2017	SLQ1172Z	0	34952	67/DS/SLQ1172Z																												
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On																												
JTDKB3FU103561319		2ZRS056117	60	Sam San Joi	26/11/2024 8.00		29/11/2024 18.00																												
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount																													
1	B	BP-MECH2 REPLACE & INSTALL SPIRAL CABLE	BP64			396.00																													
2	1	U90189-06193 GROMMET, SCREW	10.00	3.20		32.00																													
3	2	U90159-60477 SCREW, W/WASHER	10.00	3.10		31.00																													
4	3	U84307-47200 CABLE SUB-ASSY, short	1.00	1485.10		1485.10																													
<table border="1"> <thead> <tr> <th>For & on behalf of</th> <th>Customer's Signature</th> <th>Charge Summary</th> <th>Total</th> </tr> </thead> <tbody> <tr> <td>Borneo Motors (Singapore) Pte Ltd</td> <td></td> <td></td> <td>1,944.10</td> </tr> <tr> <td></td> <td>Please acknowledge receipt of vehicle</td> <td>Parts 1,548.10</td> <td>GST 9.00% 174.97</td> </tr> <tr> <td></td> <td></td> <td>Labour 396.00</td> <td></td> </tr> <tr> <td></td> <td></td> <td>Sublet 0.00</td> <td></td> </tr> <tr> <td></td> <td></td> <td>Lubrication/Fluid 0.00</td> <td>Less 0.00</td> </tr> <tr> <td></td> <td></td> <td>Others 0.00</td> <td>Amount Due 2,119.07</td> </tr> </tbody> </table>								For & on behalf of	Customer's Signature	Charge Summary	Total	Borneo Motors (Singapore) Pte Ltd			1,944.10		Please acknowledge receipt of vehicle	Parts 1,548.10	GST 9.00% 174.97			Labour 396.00				Sublet 0.00				Lubrication/Fluid 0.00	Less 0.00			Others 0.00	Amount Due 2,119.07
For & on behalf of	Customer's Signature	Charge Summary	Total																																
Borneo Motors (Singapore) Pte Ltd			1,944.10																																
	Please acknowledge receipt of vehicle	Parts 1,548.10	GST 9.00% 174.97																																
		Labour 396.00																																	
		Sublet 0.00																																	
		Lubrication/Fluid 0.00	Less 0.00																																
		Others 0.00	Amount Due 2,119.07																																

Customer Copy