

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	S INCOME INSURANCE LTD		Ref:	CS/INC24060030/Anp3	
	75 BRAS BASAH R		Date:	27/09/2024	
	INCOME CENTRE	SINGAPORE 189557	Code:	INC	
1.					
· ·	Insured Veh.	SNC 9343U	Veh. Inspected	SLT 751T	
	Policy No.	7	Coverage	0	
	Claim No.	MT/1281308-001	Excess	\$0.00	
	Assign From	CHRYLLIS QUAH	Assign Date	11/06/2024	
2.	2. Vehicle Details				
	Make & Model	MITSUBISHI ATTRAGE	C.C	1193	
	Engine No.	3A92UGK5658	Year of Reg.	17/10/2017	
	Chassis No.	MMBSTA13AJH000497	Colour	RED	
	Odometer	61361 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	185/55 R15	YOKOHAMA	6	
	L/H Front Tyre	185/55 R15	YOKOHAMA	6	
	R/H Rear Tyre	185/55 R15	YOKOHAMA	6	
	L/H Rear Tyre	185/55 R15	YOKOHAMA	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	09/06/2024	Inspection Date	11/06/2024 (18:01)	
	Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a.	5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					

ESTIMATED NORMAL PERIOD FOR REPAIR: 21 Working Days