



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 6256431

Preliminary Advice

To : Liberty Insurance Pte Ltd

Date: 28/11/2024

IVS24/2207 - SMF 8214L

Survey details

Date of loss	26/11/2024
Date of Assignment	27/11/2024
Date of survey	27/11/2024
Location of survey	CHOON HOCK MOTOR TRADING CO

Vehicle Details:

Claim Type:	THIRD PARTY
Vehicle Number	SMF 8214L
Make and Model	TOYOTA HARRIER (A)
Vehicle Type	SUV
Date of Registration	27 Nov 2018
Vehicle Colour	METALLIC BLACK
Market Value (Est)	\$79,000.00
LTA Rebate	\$39,873.00
Nett Value	\$39,127.00

Proposed/Revised repair cost:

Workshop Estimate	\$6,130.55
Revised Estimate	\$4,300.56
"Check" Items	\$464.00
Total	\$4,764.56
Number of days of repair (Est)	4 Days

Remarks:

The vehicle sustained damages at the rear n/s portion.

Damages Consistent.

Please note that the preliminary advise amount (Revised) stated are subject to consistency check, part prices and labour cost.

