

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

LKK

not Authorized
in
May
27/11/24

4 days.

1/54/700/

Name : **Mohammad Isa Bte
Mustaffa Kamar (80425613)**

Accident Date : **22-Nov-24**

shep Mr. Affurp.

Vehicle No : **FBL982D (COE: 280516-270526)**

Vehicle Model : **Yamaha FZN150**

Estimated Repair Costs

Qty	Description	Amount S(\$)
List Items		
1	Front fender	160 \$ Cpa 280.00 ✓
2	Fork inner tubes	\$ Su 640.00 X
2	Fork outer tubes	\$ n 660.00 X
1	Fork under bracket	\$ n 280.00 X
1	Front rim	\$ Su 580.00 X
1	Front brake disc	\$ n 285.00 X
1	Front rim shaft	60 \$ Cn 125.00 ✓
1	Front rim bearing	\$ n 88.00 X
2	Front signal	110 n/s \$ Cne 280.00 p c
2	Side mirror - R/L	90 \$ Bnw 160.00 ✓
1	Handle bar	\$ Bnf 285.00 ✓
1	Handle bar balancer	50 \$ Cn 105.00 ✓
1	Hand grip (1 set)	70 \$ Tora 90.00 ✓
1	Clutch lever	110 \$ Cn 125.00 ✓
2	Fuel tank side cover - R/L	290 n/s \$ cre 600.00 p c
2	Front footrest	90 n/s \$ Bnw 180.00 p c
2	Front footrest brackets	\$ n 380.00 X
2	Rear footrest	70 n/s \$ cra 140.00 p c
2	Rear footrest bracket	140 n/s \$ Bnf 280.00 p c
2	Rear tail board	200 p 400 \$ cre 560.00 ✓
1	Exhaust assy	\$ R 950.00 X
1	Exhaust end cap	60 \$ Cn 115.00 ✓
1	Exhaust protector	\$ Cn 145.00 ✓
		\$ 7,333.00
Less 10%		\$ 733.30
		\$ 6,599.70

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : **Mohammad Isa Bte
Mustaffa Kamar (80425613)**

Accident Date : **22-Nov-24**

Vehicle No : **FBL982D (COE: 280516-270526)**

Vehicle Model : **Yamaha FZN150**

Estimated Repair Costs

Special Nett Items

1	Rqr Number plate (1 set)	\$	Bnt	38.00	20
2	Fork oils	\$	11	30.00	X
2	Fork oil seals	\$	11	56.00	X
1	Steering cone (1 set)	\$	11	95.00	X
1	Rear box	\$	CWT	480.00	380
1	Rear box bracket	\$	Bnt	180.00	150
		\$		879.00	


S/No. Labour

1	To provide towing service LOD)	refer LOD	\$	X	-
2	To check wiring and reset headlamp focusing		\$	11	80.00 X
3	To repair body frame		\$	11	420.00 X
4	To provide labour		\$		480.00 300
			\$		980.00

Grand Total

\$ 8,458.70

Singapore Dollars: Eight Thousand Four Hundred Fifty-Eight and Cents: Seventy only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

9-2130
102
1917
550
700
2767