



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJZ 1019K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	REAR BUMPER	DISTORTED	547.57	547.57
1	REAR BUMPER LOWER SPOILER	DEFORMED	100.42	100.42
1	REAR BUMPER RETAINER RH	NOT NECESSARY	20.20	-
1	REAR BUMPER REINFORCEMENT	CRACKED	301.84	301.84
1	REAR BUMPER REINFORCEMENT SPONGE	NOT NECESSARY	140.44	-
2	REAR BUMPER PARKING SENSOR RH @\$183.74	DAMAGED	367.48	367.48
1	REAR END PANEL	TO REPAIR SEE LABOUR	261.32	-
1	TAILLAMP RH	NOT NECESSARY	194.00	-
	LESS 10% DISCOUNT		-193.33	-131.73
			1,739.94	1,185.58
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET REAR END PANEL SEALANT (SN)	NOT NECESSARY	60.00	-
			110.00	30.00
	<b><u>LABOUR</u></b>			
	TO PUTTY AND SPRAY PAINTING.		600.00	400.00
	WIRING CHARGES.		60.00	30.00
	TUFF COATING.	NOT NECESSARY	60.00	-
	TO REMOVE, REPLACE REVERSE SENSOR.		100.00	50.00
	LABOUR TO REMOVE REAR ACCIDENT DAMAGED PARTS IN ORDER TO REPAIRS INCLUDING PANEL BEAT AND REPLACE ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		600.00	400.00
			1,420.00	880.00
	<b>GRAND TOTAL</b>		<b>3,269.94</b>	<b>2,095.58</b>

Report Ref No. CS/INC24110585/Avh3e2(N)



<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>			<b>1,650.00</b>
---	--	--	-----------------

Report Ref No. CS/INC24110585/Avh3e2(N)

TOTAL FOR SPARE PARTS: \$ 1,849.94 \$ 1,215.58

TOTAL FOR LABOUR : \$ 1,420.00 \$ 880.00

TOTAL REPAIR COST: \$ 3,269.94 \$ 2,095.58

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.