



ESTABLISHED 1984

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD
75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557
ATTN: YEE PEI LI

Ref: CS/INC24110586/Avh3m4(N)
Date: 25/03/2025
Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKZ 7136D	Veh. Inspected	SNP 5539E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1305877-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	26/11/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2024
Chassis No.	MR2BE3BE700028584	Colour	WHITE
Odometer	62654 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55R16	MICHELIN	6 mm
L/H Front Tyre	205/55R16	MICHELIN	6 mm
R/H Rear Tyre	205/55R16	MICHELIN	6 mm
L/H Rear Tyre	205/55R16	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/11/2024	Inspect Date / Time	27/11/2024 (03:33 PM)
Survey held at	HUI HUANG HONG BAO MOTORS 2 KAKI BUKIT AVENUE 2 #02-11 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**