

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00
 Springleaf Tower
 Singapore 079909
 Tel : 6389 - 6111
 Fax : 6224 - 7478 / 7175

Quotation

DATE : 04.07.2024
 VEH NO : SLQ9089D
 MODEL : Honda Freed
 D O A : 27.06.2024
 YR REF : GBK4285L

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SLQ9089D (HONDA FREED)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
<u>NO</u>	<u>LIST ITEMS</u>		
1	Front Door - LH <i>Revised</i>	1	1,205.40 ✓
2	Front Door Lock - LH <i>new</i>	1	270.10 +
3	Front Door Weatherstripe - LH <i>new</i>	1	210.80 +
4	Front Door Glass - LH <i>new</i>	1	722.40 +
5	Front Door Glass Outer Moulding - LH <i>Revised</i>	1	95.60 ✓
6	Front Door Glass Regulator Gear - LH <i>new</i>	1	340.40 +
7	Front Door Glass Regulator Motor - LH <i>new</i>	1	399.50 +
8	Front Door Inner Trim Board - LH <i>new</i>	1	680.50 +
9	Wing Mirror - LH <i>new</i>	1	780.20 +
10	Wing Mirror Cover - LH <i>new</i>	1	75.30 +
			\$ 4,780.20
Less 20%			\$ (956.04)
			\$ 3,824.16

S/NETT ITEMS

1	Front Door Inner Trim Clips <i>new</i>	1 set	30.00 +
2	Front Door Black Tape } <i>new</i>	1 set	60.00 50
3	Front Door Visor	1	100.00 80
			190.00

Total parts

\$ 4,014.16

LABOUR CHARGE

1	To knocking out front LH side portion & renew above parts	\$ 400.00
		<i>200</i>

RE : ESTIMATE FOR ACCIDENT REPAIR SLQ9089D (HONDA FREED)

2	To putty & spray up paint works	\$	400.00 <i>300</i>
3	To check wiring	\$	50.00 <i>30</i>
4	To transfer door fittings	\$	150.00 <i>80</i>
Total Labour		\$	1,000.00
Grand Total		\$	5,014.16

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Adam C
h/s 30/08/24

03 Days.

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to commission • Third party survey is only for "not at fault" basis • No illegal motor vehicles to be repaired • Supplementary work(s) must be authorised and is subject to final approval from the repair company Acknowledged by Repairer Signature: _____ Date: _____
