



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD ONE RAFFLES QUAY #25-01 NORTH TOWER SINGAPORE 048583 ATTN: TED SEAH			Ref: CS/LIP24110592/Kvh3e2(N) Date: 18/03/2025 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNG 226M	Veh. Inspected	SLG 238C
	Policy No.		Coverage (\$)	0.00
	Claim No.	AVS24/3561	Excess (\$)	0.00
	Assign From	TED SEAH	Assign Date	27/11/2024
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ E200 (A)	c.c	1991
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.	WDD2130422A458755	Colour	METALLIC GREY
	Odometer	77117 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	245/45 R18	PIRELLI	7 mm
	L/H Front Tyre	245/45 R18	PIRELLI	7 mm
	R/H Rear Tyre	245/45 R18	PIRELLI	7 mm
	L/H Rear Tyre	245/45 R18	PIRELLI	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	15/11/2024	Inspection Date	28/11/2024
	Survey held at	TROPICAL SUCCESS AUTO CARE BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535.		
5a. Remarks				
	A)REGISTRATION DATE: 27 JUL 2018 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	