

HUP LIAN HUAT ENGINEERING WORKS

Blk 2 Defu South Street 1 #04-01
Defu Industrial City, Singapore 533755
TEL : 6282 3336 FAX : 6289 3336

not Authorized
3/12/24
2/s \$36,000
Wee Guan Engineering Pte Ltd
3 days

MSIG INSURANCE (SINGAPORE) PTE LTD
4 Shenton Way #21-01 SGX
Centre 2, Singapore 068807
ATTN : Motor Claim Department

Claim Type : Third Party
Accident Date : 19/11/2024
TP Vehicle No : SKN129J
Wee Guan Engineering Pte Ltd

ESTIMATE No :
DATE : 28/02/2025
Policy No : 2024-V5027588-VCV
Veh Reg No : XD8779D
Make & Model : ISUZU FXZ77M
Chassis No : JALFX77ME7000040
Engine No : 6UZ1484141
Reg Date : 07/05/2014

ESTIMATE OF VEHICLE NO : XD8779D

Description	Qty	List Price
-------------	-----	------------

Net Price

1 TMA Assy Section I (inner)	1 set	DIS 45,000.00 ✓
2 TMA Assy Section II (outer)	1 set	R 45,000.00 X

Total 90,000.00

Labour

Labour to dismantle TMA Assy Section I renew & refit back .
Labour to dismantle TMA Assy Section II renew & refit back .

1,000.00
1,000.00 } 800

Total 2,000.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Total \$	94,000.00
Add GST 9% \$	8,460.00
TOTAL AMOUNT \$	102,460.00