

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SND 8536G				
REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT FENDER UPPER GLASS (RH)	CUT	\$245.14	\$245.14
1	SIDE MIRROR ASSY (RH)	DENTED/CRACKED	\$1,778.45	\$1,520.80
1	SIDE MIRROR COVER (RH)	TO REPAIR SEE LABOUR	\$148.82	\$0.00
	LESS 0.00 / 25.00% DISCOUNT		\$0.00	(\$441.49)
			\$2,172.41	\$1,324.45
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	GLASS SEALANT (SN)	NECESSARY	\$50.00	\$35.00
			\$50.00	\$35.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS. INCLUSIVE OF THE REPAIR OF SIDE MTRROR COVER (RH) }		\$100.00	\$80.00
	TO SUPPLY LABOUR TO REMOVE & REFIT UP HOSTLER FOR REPAIR }		\$100.00	\$0.00
	TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA		\$100.00	\$60.00
	TO SUPPLY LABOUR TO REFIT GLASS		\$200.00	\$60.00
	TO SUPPLY DIAGNOTIC & REPROGRAMMING		\$450.00	\$120.00
			\$950.00	\$320.00
GRAND TOTAL			\$3,172.41	\$1,679.45

TOTAL FOR SPARE PARTS: \$ 2,222.41 \$ 1,359.45 TOTAL FOR LABOUR: \$ 950.00 \$ 320.00 **TOTAL REPAIR COST:** \$ 3,172.41 \$ 1,679.45

Report Ref No: CS/INC24110596/Kqh3m4

\$1,350.00

## **KSC**

(CONFIRMED)

KENNETH KONG SENG CHEONG

RECOMMENDED COST OF LUMP SUM REPAIRS

(TO ITS PRE-ACCIDENT CONDITION)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.