

Automobile Integrated Management Pte Ltd (Co.Reg.No:201605297G)

23 Kaki Bukit Ave 4, #04-01 (south wing) Kaki Bukit Vicom

Singapore 415933

Tel: 91195277 / 91198371 Email: automim.claim@gmail.com

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	C20240045/OD
Policy No:	MCV24A00021601	Date of Loss:	24/06/2024
Vehicle Reg. No.:	GQ2325C	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LEE HAN ENGINEERING PTE LTD		
Make/Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (M)	Vehicle Reg. Date:	25/03/2016
Vehicle Colour:	GOLD	Chassis No:	JN1SC2F24Z0858274
Engine No:	ZD30009550N		
Odometer:	263959 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		
Present Location:	AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (HQ)		

*Not Allowed
on
more
Excess \$600
4 days
2 days late repair 4 days*

4/5 \$3450

COST OF CLAIMS

	Amount
Parts	4,613.13
Miscellaneous Items	0.00
Labour	1,320.00
Paintwork Labour	1,200.00
Towing	0.00

Gross Total (\$\$) 7,133.13

+ GST 9.00% (\$\$) 641.98

Nett Amount (\$\$) 7,775.11

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 26 Jun 2024)
Parts: N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (M) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GQ2325C)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Wiper panel, front	0.00	0.00	DD *350.00 F ✓
2	1		*Headlamp LH	0.00	0.00	CR *350.00 F ✓
3	1		*Headlamp corner panel	0.00	0.00	DD *275.00 F ✓
4	1		*Headlamp lower panel	0.00	0.00	CR *68.75 F ✓
5	1		*Bumper, front	0.00	0.00	fresh *600.00 F ✓
6	1		*side mirror assy LH	0.00	0.00	R *375.00 F X
7	1		*side mirror cover LH	CR0/ 0.00	0.00	BYE *93.75 F ✓
8	1		*Door LH, front	0.00	0.00	DD/R *812.50 E ✓
9	1		*panel center, front	0.00	0.00	R *875.00 F X
10	1		*Cabstar badge	0.00	0.00	SW *43.75 F X
11	1		*grille center, front	0.00	0.00	CR *350.00 F ✓
Sub Total (\$\$)						4,193.75
+ Margin on L,N Items 10.00% (\$\$)						419.38
Total Parts (\$\$)						4,613.13

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	SPRAY PAINTING	New 550	1,200.00
<u>Labour Items</u>			
2	PANEL BEATING	New 400	1,200.00
3	WIRING	New 20	120.00
Gross Labour Cost (\$\$)			2,520.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

P-3062
+ 10%
3368.20
970
4338.20
202
3470.

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	Step garnish LH <i>supp</i>	<i>one</i> 162.00
Sub Total (S\$)			162.00

Estimates on Labour

There are no labour items selected.

Automobile Integrated Management Pte Ltd/GQ2325C/05/07/2024 15:38. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >