

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET

#04/#05 IOB BUILDING

SINGAPORE 049711

GBD1403U

Not Authorized

du
meras
29.11.24

1/55 7500/
take photo. Atk. rep.

5 days

ESTIMATE

DATE : 27.11.2024

VEHICLE NO : SMJ3427B

MAKE/MODEL : HONDA FIT

ACC DATE : 26.11.2024

PARTICULAR		UNIT PRICE	AMOUNT
QTY	LIST PRICE	SS	SS
1	1 FRONT BUMPER	581.20 723.60	723.60 ✓
2	1 FRONT BUMPER SIDE GRILLE - RH	62.50	62.50 ✓
3	2 FRONT BUMPER SIDE RETAINER RH/LH	45.50	91.00 ✓
4	1 FRONT DOOR RH	1,053.60	1,053.60 ✓
5	1 FRONT DOOR SIDE MIRROR	480.50 615.20	615.20 ✓
6	1 FRONT DOOR OUTER HANDLE	182.60	182.60 ✓
7	1 FRONT DOOR OUTER KEY SET	211.50	211.50 ✓
8	1 FRONT DOOR GLASS OUTER MOULDING	151.20	151.20 X
9	1 FRONT DOOR GLASS RUN CHANNEL	210.60	210.60 X
10	1 FRONT DOOR GLASS REGULATOR	291.20 491.50	491.50 ✓
11	1 FRONT DOOR GLASS GUIDE	86.90	86.90 X
12	1 FRONT DOOR INNER LOCK	286.60	286.60 ✓
13	1 FRONT DOOR INNER TRIM BOARD	761.99	761.99 ✓
14	1 FRONT DOOR INSULATOR	130.20	130.20 X
15	1 FRONT DOOR WEATHERSTRIP	141.20	141.20 ✓
16	1 FRONT DOOR CHECKER	89.50	89.50 ✓
17	2 FRONT DOOR HINGE	95.50	191.00 ✓
18	1 FRONT FENDER RH	425.10	425.10 X
19	1 FRONT FENDER INNER SHIELD	161.20	161.20 ✓
20	1 FRONT FENDER INNER PANEL MEMBER	410.60	410.60 ✓
21	1 FRONT FENDER EMBLEM	68.60	68.60 ✓
22	1 FRONT FENDER SIGNAL LAMP	58.80	58.80 X
23	1 FRONT SHOCK ABSORBER RH	410.60	410.60 ✓
24	1 FRONT LOWER ARM	376.60	376.60 ✓
25	1 FRONT KNUCKLE ARM	405.90	405.90 ✓
26	1 FRONT WHEEL HUB	210.60	210.60 ✓
27	1 FRONT WHEEL BEARING	186.90	186.90 ✓
28	1 FRONT ANIT ROLL BAR	310.50	310.50 X
29	1 FRONT ANIT ROLL BAR LINK	86.60	86.60 X
30	1 FRONT DRIVE SHAFT RH	1,210.50	1,210.50 X
BAL C/F			9,803.19

LEE BROTHERS AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
		BAL B/F	<u>9,803.19</u>
31	1 FRONT HEADLAMP RH	1,671.50	1,671.50 ✓
32	1 SIDE STILL PANEL RH	691.90	691.90 X
33	1 SIDE STILL PANEL GARNISH	586.90	586.90 ✓
34	1 REAR DOOR RH	991.60	991.60 X
			<u>13,745.09</u>
		LESS 20%	<u>2,749.02</u>
			<u>10,996.07</u>

SPECIAL NETT ITEMS

1	1 (SET) FRONT BUMPER CLIP	50.00	50.00 30
2	1 (SET) FRONT FENDER INNER SHIELD CLIP	60.00	60.00 30
3	1 FRONT SPORT WHEEL RH	650.00	650.00 400
4	1 FRONT TYRE RH	250.00	250.00 X
5	1 (SET) FRONT DOOR BLACK TAPE	120.00	120.00 60
6	1 (SET) FRONT AND REAR DOOR VISOR	350.00	350.00 60
			<u>1,480.00</u>

LABOUR CHARGES :

1	TO CHECK FRONT WIRING	50.00	20
2	TO REMOVE AND REPLACE FRONT UNDERCARRIAGE	250.00	120
3	TO PERFORM COMPUTERISE 4 WHEEL ALIGHTMENT	120.00	80
4	TO TUFF KOTE	120.00	50
5	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	1,400.00	600
6	TO PANEL BEAT, CUT, WELD , REMOVE & REPLACE DAMAGE PARTS	1,200.00	1100
			<u>3,140.00</u>

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 15,616.07

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 8535.79
20%
682864
580
1970
937804
202
7502