

(08/11/13) wef

ASS. DEC. BY: Marcus

REF:

CD/11/24/10622/4m93

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SMJ 3427B  
 at Workshop m/s: Leebroth  
 of \_\_\_\_\_  
 Insured: GRD 14034  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SMJ 3427B Yr Regn: 28/02/19  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or CAJ  
 Make: Honda Fit Hybrid c.c. 1496  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp. Reading: 175931 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: GP 513 29 353  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or ok  
 Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 205/55R16  
 R: \_\_\_\_\_

(Policy Condition)  
 Remark: **The veh had commenced its repair at the time of inspection.**

N/S	O/S

Bal. or Market Value: #58k.  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Lum Sum: 20 % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS 333d  
 Date: \_\_\_\_\_ Person Contacted: LTA 21650  
 Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or  
 Front 6 mm Rear 6 mm  
 R/Bal. \_\_\_\_\_ mm R/Bal. \_\_\_\_\_ mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 26/11/24 D.O.I. 29/11/24  
 Survey held at \_\_\_\_\_  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
ok fit, o/s Body &  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time	Action / Instruction
<u>9/11/24</u>	<u>L/S 7500 inform MR Lee</u>

Date/Time, File Pass to?  : Preli. Report  : Final Report  
 1) \_\_\_\_\_  
 Date/Time, File Return to? \_\_\_\_\_  
 2) \_\_\_\_\_

Report Format : \_\_\_\_\_  
 Lump Sum / I.B.I: (\$) \_\_\_\_\_ )

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

Add Fee:  : Site Insp (\$) )  : S + RS, \$  
 : Interview (\$) ) Photos  
 : Tech. Invs (\$) ) Others  
 : Weekend (\$) )

TOTAL \_\_\_\_\_

# LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47  
 AUTOBAY SINGAPORE 417883  
 Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

**INDIA INTERNATIONAL INSURANCE PTE LTD**  
 64 CECIL STREET  
 #04/#05 IOB BUILDING  
 SINGAPORE 049711  
GBD1403U

## ESTIMATE

DATE : 27.11.2024  
 VEHICLE NO : SMJ3427B  
 MAKE/MODEL : HONDA FIT  
 ACC DATE : 26.11.2024

Not Authorized  
 du  
 meras  
 29.11.24  
 1/58 7500/  
 take photo of the car  
 S days

PARTICULAR		UNIT PRICE	AMOUNT
QTY	LIST PRICE	SS	SS
1	1 FRONT BUMPER	581.20 723.60	DIS 723.60 ✓
2	1 FRONT BUMPER SIDE GRILLE - RH	62.50	grand 62.50 ✓
3	2 FRONT BMPER SIDE RETAINER RH/LH	45.50	als n n v/s cre 91.00 ✓
4	1 FRONT DOOR RH	1,053.60	1,053.60 ✓
5	1 FRONT DOOR SIDE MIRROR	480.50 615.20	Damage 615.20 ✓
6	1 FRONT DIIR OUTER HANDLE	182.60	air 182.60 ✓
7	1 FRONT DOOR OUTER KEY SET	211.50	Dage 211.50 ✓
8	1 FRONT DOOR GLASS OUTER MOUDLING	151.20	su 151.20 X
9	1 FRONT DOOR GLASS RUN CHANNEL	210.60	n 210.60 X
10	1 FRONT DOOR GLASS REGULATOR	291.20 491.50	Surf 491.50 ✓
11	1 FRONT DOOR GLASS GUIDE	86.90	n 86.90 X
12	1 FRONT DOOR INNER LOCK	286.60	Dage 286.60 ✓
13	1 FRONT DOOR INNER TRIM BOARD	761.99	De / trim 761.99 ✓
14	1 FRONT DOOR INSULATOR	130.20	n 130.20 X
15	1 FRONT DOOR WEATHERSTRIP	141.20	n 141.20 ✓
16	1 FRONT DOOR CHECKER	89.50	7 m 89.50 ✓
17	2 FRONT DOOR HINGE	95.50	Surf 191.00 ✓
18	1 FRONT FENDER RH	425.10	R 425.10 X
19	1 FRONT FENDER INNER SHIELD	161.20	7 m 161.20 ✓
20	1 FRONT FENDER INNER PANEL MEMBER	410.60	2 / Surf 410.60 ✓
21	1 FRONT FENDER EMBLEM	68.60	ner 68.60 ✓
22	1 FRONT FENDER SIGNAL LAMP	58.80	n 58.80 X
23	1 FRONT SHOCK ABSORBER RH	410.60	Surf 410.60 ✓
24	1 FRONT LOWER ARM	376.60	Surf 376.60 ✓
25	1 FRONT KNUCKLE ARM	405.90	Surf 405.90 ✓
26	1 FRONT WHEEL HUB	210.60	Bent 210.60 ✓
27	1 FRONT WHEEL BEARING	186.90	ner 186.90 ✓
28	1 FRONT ANIT ROLL BAR	310.50	n 310.50 X
29	1 FRONT ANIT ROLL BAR LINK	86.60	n 86.60 X
30	1 FRONT DRIVE SHAFT RH	1,210.50	n 1,210.50 X
		<b>BAL C/F</b>	<b>9,803.19</b>

# LEE BROTHERS AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
		<b>BAL B/F</b>	<u>9,803.19</u>
31	1 FRONT HEADLAMP RH	<i>1480.20</i> 1,671.50	<i>one</i> 1,671.50 ✓
32	1 SIDE STILL PANEL RH	691.90	<i>R</i> 691.90 X
33	1 SIDE STILL PANEL GARNISH	586.90	<i>de/w.in</i> 586.90 ✓
34	1 REAR DOOR RH	991.60	<i>R</i> 991.60 X
			<u>13,745.09</u>
		LESS 20%	<u>2,749.02</u>
			<u>10,996.07</u>

**SPECIAL NETT ITEMS**

1	1 (SET) FRONT BUMPER CLIP	50.00	<i>neu</i> 50.00 <i>30</i>
2	1 (SET) FRONT FENDER INNER SHIELD CLIP	60.00	<i>neu</i> 60.00 <i>30</i>
3	1 FRONT SPORT WHEEL RH	650.00	<i>recip'd</i> 650.00 <i>400</i>
4	1 FRONT TYRE RH	250.00	<i>su</i> 250.00 X
5	1 (SET) FRONT DOOR BLACK TAPE	120.00	<i>neu</i> 120.00 <i>60</i>
6	1 (SET) FRONT AND REAR DOOR VISOR	350.00	<i>neu</i> 350.00 <i>60</i>
			<u>1,480.00</u>

**LABOUR CHARGES :**

1	TO CHECK FRONT WIRING	50.00	<i>20</i>
2	TO REMOVE AND REPLACE FRONT UNDERCARRIAGE	250.00	<i>120</i>
3	TO PERFORM COMPUTERISE 4 WHEEL ALIGHTMENT	120.00	<i>80</i>
4	TO TUFF KOTE	120.00	<i>50</i>
5	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	1,400.00	<i>600</i>
6	TO PANEL BEAT, CUT, WELD , REMOVE & REPLACE DAMAGE PARTS	1,200.00	<i>1100</i>
		<u>3,140.00</u>	

**ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 15,616.07**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

*P- 8535-79*  
*20%*  
*682864*  
*580*  
*1970*  
*937804*  
*202*  
*7502*

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	333D
Vehicle Details	
Vehicle No.:	SMJ3427B
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Nov 2024
Vehicle Make:	HONDA
Vehicle Model:	FIT HYBRID 1.5 AUTO
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	LEB1435309
Chassis No.:	GP51329353
Maximum Power Output:	101.0 kW (135 bhp)
Open Market Value:	\$19,409.00
Original Registration Date:	28 Feb 2019
First Registration Date:	28 Feb 2019
Transfer Count:	2
Actual ARF Paid:	\$9,409.00 4704
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Feb 2029
PARF Rebate Amount:	\$6,586.00
Intended COE Rebate Details	
COE Expiry Date:	27 Feb 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$35,403.00
COE Rebate Amount:	\$15,064.00
<b>Total Rebate Amount:</b>	<b>\$21,650.00</b>
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 28 Nov 2024

OK



Home > Used Cars > Listing

All Category  Filter

Search



Any status  2019   
Sort by Any Status, Date Posted (Newest)

27 Vehicles

Car Make Car Model Price Range Depreciation 2019 Mileage



**Honda Fit Hybrid 1.5A** \$66,888  \$13,210 /yr  N.A.

Consignment unit! Comes with upgraded 16" sport rims. Car always parked under shelter, well maintained. GPS and Bluetooth, auto tailgate with, keyless entry and start, reverse camera. Full loan and trade in available, consignments are welcomed too. Please book an appointment with us to view this unit.

Posted 28-Nov-2024

Compare

PREMIUM AD



**Honda Fit Hybrid 1.5A** \$56,800  \$12,410 /yr  N.A.

High quality refined showroom condition unit. Fresh paintwork. All wear and tear replaced. Lowest depreciation. Lowest loan interest rate from 1.48%. Highest trade in value. Call now!

M Motors Pte Ltd | Posted 25-Nov-2024

Compare

PREMIUM AD



**Honda Fit Hybrid 1.5A** \$68,000  \$12,920 /yr

New paintwork by Kolorwerz auto shop! Choice of colour Carmat. Loan/trade in available! View strictly by appt to serve you better!

Posted 23-Nov-2024

Compare

# COMPUTERISED 4 WHEEL ALIGNMENT HUNTER DSP700

Company: LEE BROTHERS AUTOMOTIVE P/L  
 VIN: SMJ 3427 B  
 Date: 27.11.24 16:47



Factory Japan 2021.0.1 : Honda : Fit Hybrid : GP5

**Front : Left**

Actual	Before	Specified Range
-0°17'	-0°17'	-1°00' 1°00'
4°45'	4°45'	3°55' 5°55'
0°24'	0°24'	-0°09' 0°09'
14°27'	14°27'	11°30' 13°30'
14°10'	14°10'	10°30' 14°30'

**Front : Right**

Actual	Before	Specified Range
-1°32'	-1°32'	-1°00' 1°00'
5°27'	5°27'	3°55' 5°55'
0°25'	0°25'	-0°09' 0°09'
6°26'	6°26'	11°30' 13°30'
4°53'	4°53'	10°30' 14°30'

Camber  
 Caster  
 Toe  
 SAI  
 Included Angle  
 Turning Angle Diff.

**Front**

Cross Camber  
 Cross Caster  
 Cross SAI  
 Total Toe  
 Cross Turn Diff.

Actual	Before	Specified Range
1°15'	1°16'	
-0°42'	-0°42'	
8°01'	8°01'	
0°49'	0°49'	-0°17' 0°17'

**Rear : Left**

Actual	Before	Specified Range
-1°32'	-1°32'	-2°30' -0°30'
0°09'	0°09'	0°00' 0°17'

**Rear : Right**

Actual	Before	Specified Range
-1°25'	-1°24'	-2°30' -0°30'
0°14'	0°14'	0°00' 0°17'

Camber  
 Toe

**Rear**

Cross Camber  
 Total Toe  
 Thrust Angle  
 Axle Offset

Actual	Before	Specified Range
-0°07'	-0°07'	
0°23'	0°23'	0°00' 0°34'
-0°02'	-0°02'	
0mm	0mm	