

C

70741

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	292C
Vehicle Details	
Vehicle No.:	SKV7359Z
Vehicle to be Exported:	No
Intended Deregistration Date:	27 Jun 2024
Vehicle Make:	MAZDA
Vehicle Model:	BIANTE 5-DOOR WAGON 2.0L SP.6EAT
Primary Colour:	Black
Manufacturing Year:	2015
Engine No.:	PE30794488
Chassis No.:	JM6CC1071G0108552
Maximum Power Output:	111.0 kW (148 bhp)
Open Market Value:	\$18,726.00
Original Registration Date:	30 Sep 2015
First Registration Date:	30 Sep 2015
Transfer Count:	0
Actual ARF Paid:	\$18,726.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Sep 2025
PARF Rebate Amount:	\$10,299.00
Intended COE Rebate Details	
COE Expiry Date:	29 Sep 2025
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$61,300.00
COE Rebate Amount:	\$7,533.00
Total Rebate Amount:	\$17,832.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 27 Jun 2024

OK



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	25/06/2024 14:13 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	23/06/2024 23:30 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	NEAR KALLANG PARK / INDOOR STADIUM CAR PARK ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKV7359Z
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN KOON SAN
NRIC No	SXXXX292C
Email Address	tankoonsan@yahoo.com
Mobile Phone No	(Phone) +65-94500185
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Mazda
Model	Biante
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car
Transmission	Auto
CC	1998

INSURANCE COMPANY

Name of Insurance Company	United Overseas Insurance Ltd
Policy Number / Cover Note Number	DHOM130006362300

DRIVER

Name of Driver	TAN KOON SAN
NRIC No	SXXXX292C
Date Of Birth	12/04/1967
Occupation	Indoor



Driving Pass Date	29/07/1987
Driving experience	36 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-94500185
Alt. Phone Number	-
Email Address	tankoonsan@yahoo.com
Address	522 EAST COAST ROAD #17-02
Address complement	-
Postcode	458966
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collided into Property
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	1
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	No
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

On 23 June 2024 about 11+ at night, it was dark. I did not notice a pillar/stone in front and I drove straight to it. I was only moving about 30km/h as it was dark. After hitting the front, I panicked and reverse back quite a lot, didn't realised another stone/pillar behind and hit it slightly also. The front bonnet cannot closed and internally, I believed something wrong as the 'temperature' needle hit 'H' hot immediately.

The back only dented slightly.


ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


25/06/24
Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

 
Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

On 23 June 2024 about 11³⁰ pm at night,
 it was dark. I did not notice a pillar/stone
 in front and I drove straight to it.
 I was only moving about 30 km/h as it was
 dark. After hitting the front, I panicked and
 reverse back quite a lot, didn't realise another
 stone pillar behind and hit it slightly also.
 The front bonnet cannot closed and internally,
 I believe something wrong as the 'temperature'
 needle hits 'H' not immediately.
 The back only dented slightly.

Declaration

We declare the foregoing particulars are true in every respect.


 Policyholder's Signature / Date &
 Time

Driver's Signature (if driver is not the policyholder) / Date
 & Time

 *Floriane*
 Witnessed by Reporting Centre
 Personnel



FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg No.: 199501140D
GST Reg. No.: 199501140D

1 of

UNITED OVERSEAS INSURANCE LTD

146 ROBINSON ROAD #02-01

UOI BUILDING

068909

Attn: MOTOR CLAIMS DEPT

Tel: 6222 7733

Not Withheld
21 Sep &
Running After Pairs

Ex @ 8000

8 days

4/5 @ 10,700

Estimate : ES000064
Date : 27/06/2024
Vehicle No. : SKV7359Z
Vehicle Model : MAZDA BIANTE 5-DOOR WAGON
2.0L SP.6EAT
Chassis No. : JM6CC1071G0108552
Accident Date : 23/06/2024
Claim No. :
Reference : O/D
Policy No. : DHOM130006362300
Page : 1 of 3

Item	Qty	Description	Unit Price S\$	Amount S\$
1.	1	BONNET	430.00	<i>By</i> 473.00 ✓
2.	1	BONNET LOCK	95.00	<i>Div</i> 104.50 ✓
3.	2	BONNET HINGE	32.00	<i>Dis</i> 70.40 ✓
4.	1	BONNET INSULATOR CLIP	50.00	<i>By</i> 50.00 ✓
5.	2	HEADLAMP	<i>mg CM</i> 1,100.00	2,420.00 ✓
6.	1	RADIATOR SUPPORT PANEL	280.00	<i>CM</i> 303.00 ✓
7.	1	RADIATOR AUTO	<i>hours By</i> 410.00	414.10 ✓
8.	1	RADIATOR SPARE TANK	<i>Net</i> 65.00	71.50 ✓
9.	1	RADIATOR FAN COWLING ASSY	<i>CM</i> 575.00	632.50 ✓
10.	1	FRONT BRACE PANEL	30.00	<i>By</i> 33.00 ✓
11.	1	TOW COVER	20.00	<i>Net</i> 22.00 ✓
12.	1	AIR CON CONDENSER	600.00	<i>Pr</i> 660.00 ✓
13.	1	FRONT GRILLE ASSY	900.00	<i>CM</i> 990.00 ✓
14.	1	FRONT GRILLE LOGO	48.00	<i>Net</i> 52.80 ✓
15.	1	INTAKE MANIFOLD	680.00	<i>Sw</i> 748.00 ✓
16.	1	FRONT BUMPER	730.00	<i>By</i> 803.00 ✓
17.	2	FRONT BUMPER SIDE RETAINER	25.00	<i>Sw</i> 55.00 ✓
18.	1	FRONT BUMPER REINFORCEMENT	265.00	<i>By</i> 291.50 ✓

Continue to Next Page

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON - AIR

UNITED OVERSEAS INSURANCE LTD

146 ROBINSON ROAD #02-01
UOI BUILDING
068909
Attn : MOTOR CLAIMS DEPT
Tel : 6222 7733

Date : 27/06/2024
Vehicle No. : SKV7359Z
Vehicle Model : MAZDA BIANTE 5-DOOR WAGON
2.0L SP.6EAT
Chassis No. : JM6CC1071G0108552
Accident Date : 23/06/2024
Claim No. :
Reference : O/D
Policy No. : DHOM130006362300
Page : 2 of 3

Item	Qty	Description	Unit Price S\$	Amount S\$	
19.	2	FRONT BUMPER TOP CHROME	CHUM 195.00	429.00	✓
20.	2	FRONT BUMPER LOWER CHROME STICKER	M 48.00	105.60	✓
21.	1	FRONT BUMPER CLIP	M 60.00	60.00	✓
22.	1	FRONT NUMBER PLATE	R 45.00	45.00	✓
23.	1	FRONT BUMPER UNDER COVER	P 65.00	71.50	X
24.	1	FRONT ENGINE UNDERCOVER	L 185.00	203.50	X
25.	2	HEADLAMP LOWER BRACKET	CRM 65.00	143.00	✓
26.	1	TAILGATE	R 750.00	825.00	✓
27.	1	TAILGATE GLASS INNER MOULDING	NN 40.00	40.00	X
28.	1	TAILGATE SEALANT	M 40.00	40.00	✓
29.	1	TAILGATE EMBLEM - SKYACTIV	40.00	M 44.00	✓
30.	1	TAILGATE CHROME HANDLE	SM 235.00	258.50	X
31.	1	TAILGATE CENTRE GARNISH (WITH LOGO)	750.00	CRM 825.00	✓
32.	7	CLIP FASTENER	2.00	M 15.40	✓
33.	2	CLIP STOPPER	10.00	SM 22.00	X
34.	1	REAR BUMPER	485.00	R 533.50	✓
35.	1	REAR BUMPER CLIP	60.00	M 60.00	✓
36.	1	REAR BUMPER CENTRE CHROME STICKER	85.00	M 93.50	✓

Continue to Next Page

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg



FALCON-AIR

FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg No: 199501140D
GST Reg No: 199501140D

1 of 1

UNITED OVERSEAS INSURANCE LTD

146 ROBINSON ROAD #02-01

UOI BUILDING

068909

Attn: MOTOR CLAIMS DEPT

Tel: 6222 7733

Estimate : ES000064
Date : 27/06/2024
Vehicle No. : SKV7359Z
Vehicle Model : MAZDA BIANTE 5-DOOR WAGON
2.0L SP.6EAT
Chassis No. : JM6CC1071G0108552
Accident Date : 23/06/2024
Claim No. :
Reference : O/D
Policy No. : DHOM130006362300
Page : 3 of 3

Item	Qty	Description	Unit Price S\$	Amount S\$
37.	2	REAR BUMPER CHROME STICKER	55.00	121.00
38.	1	REVERSE SENSOR	250.00	250.00
39.	1	TO REMOVE/REFIX REVERSE SENSOR TO NEW BUMPER	50.00	50.00
40.	1	TO TRANSFER TAILGATE MECHANISM	100.00	100.00
41.	1	TO FOCUS HEADLAMP AND CHECK WIRING	50.00	50.00
42.	1	TO VACUUM, REOIL AND REGAS AIR CON	120.00	120.00
43.	1	TO REMOVE/REFIX TAILGATE GLASS	120.00	120.00
44.	1	TO REMOVE/REPLACE RADIATOR SUPPORT PANEL, REPAIR FRONT FENDERS, FRONT INNER PANEL, REAR END PANEL INCLUDING REPLACEMENT OF PARTS	1,400.00	1,400.00
45.	1	TO SPRAY PAINTING ON BONNET, BONNET HINGES, LH/RH FRONT FENDERS, FRONT INNER PANEL, FRONT BUMPER, TAILGATE, REAR END PANEL, REAR BUMPER	1,700.00	1,700.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:	Sub Total	S\$	15,929.80
Date:	GST @ 9%	S\$	1,433.68
	Total	S\$	17,363.48

SINGAPORE DOLLAR SEVENTEEN THOUSAND THREE HUNDRED SIXTY THREE AND CENTS FORTY EIGHT ONLY

Notes:

1. All cheques should be crossed and made payable to FALCON-AIR AUTO SERVICES PTE LTD
2. Goods sold are neither returnable nor refundable. Otherwise a cancellation fee of 20% on purchase price will be imposed.

Accepted by

FALCON - AIR AUTO SERVICES PTE LTD
(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office: Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862

Branches: Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop (Blk 1/Blk K) S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg