

MCR Motors Pte Ltd

8 Kaki Bukit Ave 4 #01-50, Premier @ Kaki Bukit Singapore 415875

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **GBK 9405A**
 Made : Toyota
 Model : Hiace DX 2.8 Auto
 Chassis No : GDH2011053057

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear Bumper / BR	1	\$ 501.60	\$ 501.60 /
2	Rear Bumper Step Panel / DD	1	\$ 365.00	\$ 365.00 /
3	Rear Bumper Lower Bracket / BT	2 X	\$ 28.20	\$ 56.40 / 112.80
4	Rear Bumper Side Retainer RH / BR	1	\$ 25.30	\$ 25.30 /
5	Rear Bumper Side Retainer LH / BR	1	\$ 25.30	\$ 25.30 /
6	Rear End Panel Inner / DD	1	\$ 1,198.20	\$ 820 / 1,198.20
7	Rear End Panel Outer / DD	1	\$ 588.30	\$ 588.30 /
8	Rear End Panel Top Garnish (metal) / BT	1	\$ 165.00	\$ 165.00 /
9	Rear End Panel Side RH X R	1	\$ 362.10	\$ 362.10
10	Rear End Panel Side LH X R	1	\$ 362.10	\$ 362.10
11	Rear Floor Panel Mat X nn	1	\$ 796.00	\$ 796.00
12	Rear Floor Panel X R	1	\$ 1,960.00	\$ 1,960.00
13	Rear Tailgate / DD	1	\$ 2,443.20	\$ 1985 / 2,443.20
14	Rear Tailgate Emblem / MC	1	\$ 72.20	\$ 72.20 /
15	Rear Tailgate Windscreen Glass / BR	1	\$ 1,451.30	\$ 1351 / 1,451.30
16	Rear Tailgate Inner Cardboard / TN	1	\$ 196.00	\$ 196.00 /
17	Rear Tailgate Inner Center Locking Control X / BT	1	\$ 264.00	\$ 264.00 /
18	Rear Tailgate Mechanism Lock / BT	1	\$ 299.60	\$ 264 / 299.60
19	Rear Tailgate Mechanism Lock Striker X nn	1	\$ 55.00	\$ 55.00
20	Rear Tailgate Outer Garnish / CU / BR	1	\$ 298.00	\$ 298.00 /
21	Rear Tailgate Rubber Guide Stopper X nn	2	\$ 41.80	\$ 83.60
22	Rear Tailgate Rubber Cap X nn	2	\$ 19.30	\$ 38.60
23	Rear Tailgate Weatherstrip / TN	1	\$ 440.80	\$ 395 / 440.80
24	Rear Tailgate Weatherstrip Protector X nn	1	\$ 217.00	\$ 217.00
25	Rear Taillamp Assembly RH / BR	1	\$ 354.80	\$ 354.80 /
26	Rear Taillamp Assembly LH / BR	1	\$ 354.80	\$ 354.80 /
27	Rear Taillamp Lower Garnish RH / BR	1	\$ 170.00	\$ 170.00 /

28	Rear Taillamp Lower Garnish LH	✓ BR	1	\$	170.00	\$	170.00	✓
29	Rear Taillamp Lower Garnish Retainer RH	X nn	1	\$	60.00	\$	60.00	
30	Rear Taillamp Lower Garnish Retainer LH	✓ BR	1	\$	60.00	\$	60.00	✓
31	Rear Taillamp Panel RH	X R	1	\$	300.00	\$	300.00	
32	Rear Taillamp Panel LH	X R	1	\$	300.00	\$	300.00	
33	Rear Side Panel Outer RH	X nn	1	\$	2,194.90	\$	2,194.90	
34	Rear Side Panel Outer LH	X R	1	\$	2,194.90	\$	2,194.90	
35	Rear Side Panel Inner RH	X nn	1	\$	1,070.20	\$	1,070.20	
36	Rear Side Panel Inner LH	X nn	1	\$	1,070.20	\$	1,070.20	
37	Rear Side Lower Corner Inner Panel RH	X nn	1	\$	187.50	\$	187.50	
38	Rear Side Lower Corner Inner Panel LH	X nn	1	\$	187.50	\$	187.50	
39	Rear Side Panel Inner Trim Board RH	X nn	1	\$	198.40	\$	198.40	
40	Rear Side Panel Inner Trim Board LH	X nn	1	\$	198.40	\$	198.40	
41	Rear Side Inner Lower Panel RH	X nn	1	\$	1,140.40	\$	1,140.40	
42	Rear Side Inner Lower Panel LH	X nn	1	\$	1,140.40	\$	1,140.40	
43	Rear Side Panel Air Vent RH	X nn	1	\$	86.30	\$	86.30	
44	Rear Side Panel Air Vent LH	X nn	1	\$	86.30	\$	86.30	
45	Rear Exhaust Pipe	X nn	1	\$	442.00	\$	442.00	
46	Rear Exhaust Pipe Gasket	X nn	1	\$	18.00	\$	18.00	
47	Rear Exhaust Pipe Mounting	X nn	1	\$	25.00	\$	25.00	
48	Rear Spare Tyre Carriage	X nn	1	\$	237.97	\$	237.97	
49	Rear Spare Tyre Carriage Bracket	X nn	1	\$	243.10	\$	243.10	
50	Rear Spare Tyre Carriage Screw	X nn	1	\$	68.30	\$	68.30	
				Parts Sub Total :		\$	24,880.37	
				25% Discount		\$	6,220.09	
				PARTS TOTAL :		\$	18,660.28	

8,481.70

-25%

6,361.27

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Rear Number Plate	✓ BR	1	\$ 50.00
2	Rear Bumper Clips - Set	✓ MC	1	\$ 50.00
3	Rear Taillamp Clips - Set	X nn	1	\$ 50.00
4	Rear Taillamp Lower Garnish Clips - Set	X nn	1	\$ 50.00
5	Rear End Panel Top Garnish Clips - Set	X nn	1	\$ 50.00
6	Rear Tailgate Outer Garnish Clips - Set	✓ MC	1	\$ 30.00
7	Rear Tailgate Inner Board Clips - Set	✓ MC	1	\$ 50.00
8	Rear Tailgate Windscreen Glass Sealant	✓ MC	1	\$ 150.00
9	Rear Side Panel Windscreen Glass Sealant	X nn	1	\$ 150.00
10	Rear Tailgate "70km/h" Sticker	✓ MC	1	\$ 50.00
11	Rear Tailgate Sealant	✓ MC	1	\$ 150.00
12	Rear End Panel Sealant	✓ MC	1	\$ 150.00

13	Rear Side Panel Outer Sealant	X nn	1	\$ 150.00	\$ 150.00
14	Rear Side Panel Inner Sealant	X nn	1	\$ 150.00	\$ 150.00
15	Rear Side Lower Panel Sealant	X nn	1	\$ 150.00	\$ 150.00
16	Rear Side Panel Inner Trim Board Clips - Set	X nr1	1	\$ 50.00	\$ 50.00
17	Rear Inner Rack - Aftermarket	X (thru hand wind)	1	\$ 2,500.00	\$ 450 2,500.00
18	Rear Bumper Reverse Sensor - Set	✓ BR	1	\$ 250.00	\$ 200 250.00
19	Rear Tailgate Reverse Camera	X nn	1	\$ 500.00	\$ 500.00
860				SPECIAL NETT TOTAL :	\$ 4,730.00

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts	\$ 1000 2,400.00
2	To Spray Paint Affected Areas	\$ 800 2,000.00
3	Wiring & Bulb Check	\$ 30 100.00
4	To Remove & Refix Rear Side Panel Windscreen Glass	\$ 120 X 150.00
5	To Remove & Refix Rear Tailgate Windscreen Glass	\$ 120 150.00
6	To Transfer Rear Tailgate Mechanism	\$ 50 150.00
7	To Remove & Refix Rear Tailgate Reverse Camera	\$ 30 150.00
8	To Remove & Refix Rear Bumper Reverse Sensor	\$ 20 120.00
9	To Remove & Refix Rear Exhaust Pipe to facilitate repairs	\$ X 150.00
10	To Remove & Refix Interior Upholstry to facilitate repairs	\$ X 200.00
11	To apply anti rust on affected parts	\$ 30 250.00
12	To Conduct Water Leak Test	\$ X 100.00
13	To Send Diagnostic & Reset Control Unit. Programming & Calibration	\$ X 480.00
2080		LABOUR TOTAL : \$ 6,400.00

Steve (LKK)
 3/12/24, 11-31 on
 m R
 L/S
 y AL y
 8 days

PARTS TOTAL : \$ 18,660.28
 SPECIAL NETT TOTAL : \$ 4,730.00
 LABOUR TOTAL : \$ 6,400.00
 GRAND TOTAL : \$ 29,790.28

9301.27

L/S - 7,441.01
 = 7450

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____