

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/INC24/20012/4vh3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBJ 4649B

at Workshop m/s Munt Alambur

of 2m

Insured: SLK 63226

Policy No. _____

Claims No. MT/1305762-002


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**



Bal. or Market Value: \$60k.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 7586

Date: _____ Person Contacted: Vehicle: IN / OUT

Date / Time _____ Action / Instruction Dep 1 Yk

23-12-24 d/s \$4800 in hand Tony (red 3323, 40%)

Veh No: GBJ 4649B Yr Regn: 29/04/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (M)

Make: Toyota hiace c.c. 2982

Colour: silver A/C: Insured / Std / NI / NA

Sp.Reading: 39448 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFHT029 X 00248932

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 23/11/24 D.O.I. 3/12/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Frt

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐
☐

: Preli. Report

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

_____ S + RS, _____ St

Photos

Others

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	758B
Vehicle Details	
Vehicle No.:	GBJ4649B
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Dec 2024
Vehicle Make:	TOYOTA
Vehicle Model:	HIACE VAN TURBO 5DR MT
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	1KD2852196
Chassis No.:	JTFHT02PX00248932
Maximum Power Output:	-
Open Market Value:	\$28,136.00
Original Registration Date:	29 Apr 2019
First Registration Date:	29 Apr 2019
Transfer Count:	0
Actual ARF Paid:	\$1,407.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	28 Apr 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$22,768.00
COE Rebate Amount:	\$10,024.00
Total Rebate Amount:	\$10,024.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 03 Dec 2024

OK



Home>Used Cars>Listing

All Category



Search

Save Search



Any status ☒ 2019 ☒
Sort by Any Status, Date Posted (Newest)

40 Vehicles

Car Make

Car Model

Price Range

Depreciation

2019

Mileage



Toyota Hiace 3.0M **\$66,800** \$13,850 /yr 30-Sep-2019 (4yrs 9mths COE left) N.A. 2,982 cc 2 Owners Diesel

Ready stock unit! 5 doors manual Toyota Hiace! Paintwork & upholstery! Very well maintain unit! 100% no repairs needed! Trade in and scrap acceptable! 0 Down avail!

Posted 02-Dec-2024 ☐ Compare



Toyota Hiace 3.0A **\$62,300** \$13,870 /yr 31-May-2019 (4yrs 5mths COE left) 117,000 km 2,982 cc 1 Owner Diesel

Genuine mileage. Brand new carpet floorboard done. Well maintained. Automatic transmission. Flexible loan and financing available.

Posted 30-Nov-2024 ☐ Compare



Toyota Hiace 3.0M **\$61,800** \$14,030 /yr 30-Apr-2019 (4yrs 4mths COE left) N.A. 2,982 cc 3 Owners Diesel

Cheapest diesel Hiace in the market! Low mileage! Diesel turbo engine! Immaculate condition! Very well maintained exterior and interior! Immediate handover! 100% loan! Call us to test drive now!

Net Link Partners Pte Ltd|Posted 30-Nov-2024 ☐ Compare

Compare

HUAT AUTOMOBILE AIR CON SERVICE

BLK 3007 Ubi Road 1 #01-404

Singapore 408701 Tel 67461868 Fax 67462065

Not Authorized
on
3/12/24
1/5 4800
4 days
whatsapp to Mr. 127

VEHICLE No: GBJ 4649B

1PC	FRONT BUMPER	DIS	\$721.30	✓
1PC	FRONT BUMPER SIDE BRACKET N/S	CNE	\$145.50	✓
1PC	FRONT BUMPER SIDE GRILLE N/S	11	\$122.80	X
1PC	HEADLAMP N/S	CNE	\$1,390.10	✓
1PC	FRONT GRILLE ASSY	CNE	\$645.20	✓
1PC	FRONT CORNER PANEL N/S	Ref/3w	\$422.10	✓
1PC	FRONT DOOR VIEW MIRROR N/S	un	\$485.20	X
1PC	FRONT DOOR N/S	DD/Beat	\$2,655.30	✓
1PC	FRONT DOOR OUTER PILLAR N/S	R	\$899.10	X
1PC	FRONT STEP PANEL GARNISH N/S	ant/De	\$211.80	✓
1PC	FRONT STEP PANEL N/S	R	\$245.60	X
			\$7,944.00	
LESS 25%			\$5,958.00	

S.NETT ITEM

1SET	FRONT BUMPER CLIPS	Ref	\$40.00	30 S/N
1SET	FRONT DOOR 'ROC' STICKER N/S	Ref	\$35.00	✓ S/N

TO CHECK WIRING	\$50.00	20
TO SPRAY RUST PROOFING	\$80.00	30
TO DISMANTLE & REFIX FRONT WINDSCREEN	\$100.00	X
TO DISMANTLE & REFIX FRONT DOOR MECHANISM	\$80.00	50
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$880.00	400
TO PUTTY & SPRAY PAINTING	\$900.00	800
TOTAL	\$8,123.00	

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-6191-3
252
4643.48
65
1300
6008.48
282
4806