



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS LONPAC INSURANCE BHD		Ref:		CS/LPC24060309/Uvh3e2
300 BEACH ROAD		Date:		30/07/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555		Code:		LPC2
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
<b>Insured Veh.</b>	XD 1061L	<b>Veh. Inspected</b>	XE 2068G	
<b>Policy No.</b>	-	<b>Coverage</b>	0	
<b>Claim No.</b>	23/24/24/VC05/029433	<b>Excess</b>	\$0.00	
<b>Assign From</b>	CHARMAINE KONG	<b>Assign Date</b>	28/06/2024	
<b>2. Vehicle Details</b>				
<b>Make &amp; Model</b>	SCANIA P360	<b>C.C</b>	12742	
<b>Engine No.</b>	6939301	<b>Year of Reg.</b>	15/08/2016	
<b>Chassis No.</b>	YS2P6X40005423546	<b>Colour</b>	WHITE	
<b>Odometer</b>	1433323 KM	<b>Steering</b>	IN ORDER	
<b>Brakes</b>	IN ORDER	<b>General</b>	GOOD	
<b>Modification(s)</b>	RIMS: NIL			
<b>3. Conditions of Tyres</b>				
	<b>Size</b>	<b>Make</b>	<b>Balance (mm)</b>	
<b>R/H Front Tyre</b>	295/80R22.5	GITI	6/6/6/6	
<b>L/H Front Tyre</b>	295/80R22.5	GITI	6/6/6/6	
<b>R/H Rear Tyre</b>	295/80R22.5 (D/D)	GITI	6/6/6/6	
<b>L/H Rear Tyre</b>	295/80R22.5 (D/D)	GITI	6/6/6/6	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
<b>Accident Date</b>	24/06/2024	<b>Inspection Date</b>	02/07/2024	
<b>Survey held at</b>	HUP LIAN HUAT ENGINEERING WORKS - 38 DEFU LANE 9, DEFU INDUSTRIAL ESTATE, SINGAPORE 539278			
<b>5a. Remarks</b>				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.				
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				