

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	LONPAC INSURAN		Ref:	CS3/LPC24120025/Rvh3m4	
	300 BEACH ROAD		Date:	11/12/2024	
	#17-04/07 THE CON	ICOURSE SINGAPORE 199555	Code:	LPC2	
1.		Policy Particulars :- PRE-REPAIR SURVEY			
••	Insured Veh.	GBK 138E	Veh. Inspected	XB 8870H	
	Policy No.	-	Coverage	0	
	Claim No.	24/24/24/VC05/030272	Excess	\$0.00	
	Assign From	GERALD POH	Assign Date	03/12/2024	
2.	. Vehicle Details				
	Make & Model	MITSUBISHI FUSO FP70HDR2VDEA	c.c	10677	
	Engine No.	470912C0737682	Year of Reg.	29/11/2022	
	Chassis No.	FP70HDA20045	Colour	BLUE	
	Odometer	63030 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	FAIR	
	Modification(s)	RIMS: NIL			
3.	. Conditions of Tyres				
		Size	Make	Balance (mm)	
	R/H Front Tyre	295/80R22.5	BRIDGESTONE	8	
	L/H Front Tyre	295/80R22.5	BRIDGESTONE	8	
	R/H Rear Tyre	295/80R22.5 (D)	BRIDGESTONE	8/8	
	L/H Rear Tyre	295/80R22.5 (D)	BRIDGESTONE	8/8	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
5.	General Information				
	Accident Date	02/12/2024	Inspection Date	03/12/2024 (17:09)	
	Survey held at	YEE KEONG MOTOR ENGINEERING NO: 14 PENJURU ROAD . SINGAPORE 609125			
5a. Remarks					
A) MARKET VALUE: \$181,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$40,301.00=NETT VALUE: \$140,699 B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.					

MRB

MOHAMMED RASUL BIN MOHD YUNUS

D) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.