

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

TP INC.
Xiao Chen.

ESTIMATE OF REPAIR

Veh# : YN9657B

Model:

HINO

Accident Date : 28/11/2024

(30/10/2015 - 29/10/2025)

Location : JOO KOON WAY

3P:

XD3906L (NTUC)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Rear carrier <i>crushed</i>		12,000.00	3500
2	1 pc	Rear tailgate 60 KM/H sticker <i>new</i>		25.00	x
3	1 pc	Rear tailgate 23 PAX sticker <i>new</i>		25.00	x
4	1 pc	Rear tail gate sticker <i>new</i>		150.00	x
5	1 pc	Rear canopy assy <i>new</i>		8,500.00	2200
6	1 pc	Rear mud flap <i>new</i>		600.00	350
7	1 pc	Front Rh air duct <i>Dehnd</i>	710.20		
8	1 pc	Front Rh B pillar <i>Dehnd</i>	1910.20	910	
9	1 pc	Front door RH <i>Repair</i>	1482.00	x	
10	1 pc	Front door mechanism lock RH <i>new</i>	778.50	x	
11	1 pc	Front door inner plastic seal cover RH <i>new</i>	33.90	x	
12	1 pc	Front door guide rubber stopped RH <i>new</i>	8.40	x	
13	1 pc	Front door weatherstrip RH <i>new</i>	363.10	182	
14	1 pc	Front door RH advertisement <i>new</i>		300.00	
15	1 pc	Front Rh mud flap rear <i>Dehnd</i>	210.40		
Sub Total:			5,496.70	21,600.00	0
			25%	0%	0%
After Less %:			4,122.53	21,600.00	0
Labour					
1		To remove & refix accident damaged parts & realign affected area.		1200.00	600
2		To remove & refix door mechanism.		60.00	x
3		To remove & refix deck carrier, canopy & other attachment parts.		1200.00	600
4		To repair damage parts		2400.00	x
5		To spray paint on accident affected area.		1400.00	600
Sub-Total:				6,260.00	
LKK Auto Consultants hence notify the Repairer of the following:			Total:	31,982.53	
After less 20%:				25,586.02	

Refer to bill

1620.20

1215.15

6230

1800

Chan San Choon
Director
DipEng, AAE, MIMI, MSAE (Aust)

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer



Adrian C
1/5 03/12/24
08 hrs.

total 9245.15
1/5: 741C