

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBL 1064Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAIL LAMP RH	BROKEN	367.70	367.70
1	REAR BUMPER	BROKEN	545.80	545.80
10	REAR BUMPER CLIPS	NECESSARY	55.00	30.00
1	REAR BUMPER RETAINER - RH	BROKEN	46.00	46.00
1	COVER, REAR BUMPER, UPPER - RH	BROKEN	101.20	101.20
1	COVER, REAR BUMPER, UPPER RETAINER - RH	NOT NECESSARY	41.60	-
1	REAR FENDER DOOR - RH	TO REPAIR SEE LABOUR	1,675.00	-
	LESS 25% DISCOUNT		-708.07	-272.67
			2,124.23	818.03
	<u>LABOUR</u>			
	TO CHECK WIRING.		100.00	30.00
	TO DISMANTLE AND REPLACE OF THE ACCIDENT DAMAGED PARTS; TO HEAT/WELD, CUT-OFF REAR FENDER DOOR, REAR BUMPER, TAIL LAMP & COVER REAR BUMPER ETC INLCUDING KNOCKING, REPAIR, RESHAPE AND ADJUST OF SAME. INCLUSIVE OF THE REPAIR OF REAR FENDER DOOR - RH.		800.00	400.00
	TO PUTTY AND SPRAY PAINTING ON REAR FENDER DOOR, REAR BUMPER & REAR COVER & ACCIDENT PANELS INCLUDING KNOCKING, REPAIR, RESHAPE AND ADJUST OF SAME.		1,000.00	500.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.		300.00	30.00
			2,200.00	960.00
	GRAND TOTAL		4,324.23	1,778.03
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,400.00

Report Ref No. CS/INC24120035/Eqh3m4(N)

TOTAL FOR SPARE PARTS: \$ 2,124.23 \$ 818.03 TOTAL FOR LABOUR: \$ 2,200.00 \$ 960.00 TOTAL REPAIR COST: \$ 4,324.23 \$ 1,778.03

CHEN TSUE YEE

Automotive Assessor

(CONFIRMED)

h

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.